# **RENESAS** Tool News

# RENESAS TOOL NEWS on January 16, 2012: 120116/tn1

# Note on Using R32C/100 E30A Emulator Debugger V.1.02 Release 00

When using R32C/100 E30A Emulator Debugger V.1.02 Release 00, take note of the problem described below.

### 1. Problem

If programs are loaded on external flash memory, indefinite values are written to a portion of the RAM area. The RAM area involved in this problem is the one that follows the Work RAM and is of the same size as it.

NOTE: The size of the Work RAM is automatically calculated by the External Flash Definition Editor (EFE) and displayed on it.

The following illustration explains the RAM area involved:

#### ?

## 2. Workaround

To avoid this problem, install the problem-fixed firmware by following these steps:

- (1) Before installing the firmware, make sure that R32C/100 E30A Emulator Debugger V.1.02 Release 00 has already been installed. Otherwise, update the debugger to V.1.02 Release 00.
- (2) If two or more emulator debuggers have been installed by using the multi-installation control of High-performance Embedded Workshop, make R32C/100 E30A Emulator Debugger V.1.02 Release 00 active.

(3) Download FW\_INST\_HEW\_R32C100E30AV102.exe(2.98 MB), the installer of the

problem-fixed firmware, from HERE.

(4) Execute FW\_INST\_HEW\_R32C100E30AV102.exe; follow the instructions on-screen to install the firmware.

# NOTICES:

- 1. If the firmware is installed in the environment of Windows Vista or Windows 7, the message saying "This program might not have [been] installed correctly" may appears in Program Compatibility Assistant after the installation has been completed. If so, select "This program [has been] installed correctly."
- 2. If you have installed the firmware into any version of R32C/100 E30A emulator debugger except V.1.02 Release 00, follow these steps to restore the installation:
  - (1) Delete the FFWE30A.dll file under the ¥Tools¥Renesas¥DebugComp¥ platform¥PDTarget¥PD100E30A folder, where High-performance Embedded Workshop has been installed.
  - (2) Rename the FFWE30A.dll.bak file under the above folder to FFWE30A.dll.

Note that if you have made incorrect installation twice or more times, the above restoration is impossible.

#### [Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.