RENESAS

ZMID4200

Calibration and Linearization Manual - Analog Output

Contents

1.	Intro	duction			
2.	ZMIC	04200 Ca	alibration and Linearization Theory	3	
	2.1	Spa, Po	os0, and Pos1 Registers		
	2.2	Nonline	arity Error Correction	5	
	2.3	Zero-Po	oint Offset and Slope Calibration	6	
		2.3.1.	Zero Offset Correction	6	
		2.3.2.	Slope Correction	7	
		2.3.3.	Coil Offset Compensation		
3.	Theo	ory for C	alibration and Linearization on the Analog Output	9	
	3.1	Zero Ot	ffset and Slope Calibration		
	3.2	Referer	nce Angle Calculation		
	3.3	Determ	ining the Correction Factor for Linearization	12	
4.	Clan	nping An	alog Output for the ZMID4200	13	
	4.1	The Re	elationship between the Internal Value and the Output		
	4.2	Applyin	g the Clamping Process	14	
		4.2.1.	Calibration Process	14	
		4.2.2.	Register Clamping	14	
	4.3	Proper	Clamping Requirements	15	
	4.4	4 Clamping via Calibration			
	4.5	5 Clamping via Register Clamping			
		4.5.1.	Register Clamping Low	15	
		4.5.2.	Register Clamping High		
	4.6	3 Calibration Clamping vs. Register Clamping 1			
5.	Requ	uirement	s for Measurement of SPA and Analog Output When Using the <i>On</i>	eStepCalibration	
Alg	orithn	n			
	5.1	EEPRC	OM Configuration before Performing the Measurement		
6.	One	StepCali	bration Automatic Calibration and Linearization		
7.	Valio	dation: E	rror Calculation after Calibration and Linearization	20	
8.	Revi	sion His	tory		

Figures

Figure 1. Calibration and Linearization Flow Diagram	4
Figure 2. ZMID4200 Data Operations Block Diagram	5
Figure 3. Correction Points	5
Figure 4. Correction Curve	6
Figure 5. Example of Pos0 Values before and after Zero-Offset Correction	7

Figure 6. Slope Correction Example	8
Figure 7. Offset Compensation	9
Figure 8. Pos1 Output Mapped to 5% to 95% VDDE (No Clamping)	13
Figure 9. Clamping in an Output of 20% to 80%VDDE and Clamping in Pos1 to 16.667% to 83.33% FS	14
Figure 10. Difference between Calibration and Register Clamping	17
Figure 11. Inputs and Outputs for OneStepCalibration	19
Figure 12. General Flow Diagram for Using Internal Values for Calibration and Linearization	19
Figure 13. Flow Diagram When the Analog Output is used for Calibration and the Linearization	19

Tables

Table 1. Correction Factors	5
Table 2. Example of Ideal Data	11
Table 3. Correction Factor Calculation	12

1. Introduction

This document explains the calibration and linearization process for the ZMID4200 using the analog output; it describes in detail the available algorithms and tools, and the considerations needed for correct calibration and linearization.

Recommendation: Read the ZMID4200 Datasheet before using this document.

Important: These procedures are specifically for linearization and calibration using the analog output (the SOUT pin) or Spatialangle (SPA) that is read directly from register.

This document has three main parts:

- Theory and examples
- Considerations for correct measurements and clamping
- The OneStepCalibration algorithm for automatic calibration and linearization, which includes the algorithm for clamping calculations

For a correct calibration and linearization, a measurement of the target position during a complete sweep of the target is needed. Section 5 discusses the important considerations for a correct measurement.

The OneStepCalibration algorithm is designed for a fast and accurate calibration and linearization. The algorithm needs only a small number of configuration parameters, and it can function with SPA or analog output data.

OneStepCalibration algorithm is implemented in the following software:

- ZMID4200 Graphical User Interface (GUI)
- Python® 1 using DLL (refer to the ZMID4200 User Guide: Calibration and Linearization with Python and the DLL for details)
- LabVIEW^{™ 2} using DLL (refer to the ZMID4200 User Guide: Calibration and Linearization Using LabView and the Calibration DLL for details)

2. ZMID4200 Calibration and Linearization Theory

The flow diagram in Figure 1 shows the steps for calibration and linearization. Note: The flow that is implemented in the *OneStepCalibration* algorithm is different.

¹ Python[™] is a trademark of the Python Software Foundation.

² LabVIEW[™] is a trademark of National Instruments.



Figure 1. Calibration and Linearization Flow Diagram

2.1 Spa, Pos0, and Pos1 Registers

The processing of data in the ZMID4200 is represented in Figure 2.

Important registers:

- The Spa register represents the position value of the target without any calibration or linearization.
- The Pos0 register represents the position value of the target after calibration for slope and zero offset.
- The *Pos1* register represents the position value of the target after calibration (slope and zero offset) and after linearization (corrections at 9 data points).



Figure 2. ZMID4200 Data Operations Block Diagram

2.2 Nonlinearity Error Correction

The value of the measured position after calibration is stored in the *Pos0* register (shadow word register (SWR) address 19_{HEX} ; read only). *Pos0* is a 16-bit value covering a range of output values $[0, 2^{16} - 1]$.

The measurement output range of 2¹⁶ is divided into 8 sections. Each section has a range of 2¹³, and the boundaries are the correction points.

Correction points are fixed, and their values are expressed with respect to the maximum position output value 2¹⁶. The linearization procedure is a "one-dimensional" procedure where only the values for the y-coordinate (i.e., the measured position values) can be corrected to match the ideal measurement curve. The position values of the correction points for the Y coordinates are defined by the EEPROM (E2P) address range 03_{HEX} to 07_{HEX}.



Figure 3. Correction Points

The Y correction factor is a number in the range of ± 127 decimal, i.e., $\pm 6.2\%$ full scale (FS), and it is applied on the 11 MSB (most significant position bits) of the measured position.

ſS

Parameter	x-coord (Fixed)	y-coord Range (Variable/11 MSB)
Corr0	0	±127 _{DEC}
Corr1	$1 \times 2^{13} = 8192_{\text{DEC}}$	±127 _{DEC}
Corr2	$2 \times 2^{13} = 16384_{\text{DEC}}$	±127 _{DEC}
Corr3	$3 \times 2^{13} = 24576_{\text{DEC}}$	±127 _{DEC}
Corr4	$4 \times 2^{13} = 32768_{\text{DEC}}$	±127 _{DEC}
Corr5	$5 \times 2^{13} = 40960_{\text{DEC}}$	±127 _{DEC}
Corr6	$6 \times 2^{13} = 49152_{\text{DEC}}$	±127 _{DEC}
Corr7	$7 \times 2^{13} = 57344_{\text{DEC}}$	±127 _{DEC}
Corr8	$8 \times 2^{13} = 65536_{\text{DEC}}$	±127 _{DEC}

Each section is identified by two correction points, so a linear interpolation function can be defined between each pair of corrections points. The set of linear interpolation functions connecting the correction points defines a linear piecewise function expressing the correction function over the whole measurement range of 2¹⁶.

Applying the correction function to position value *Pos0* after the zero-point offset and slope calibration can improve the linearity by more than a factor of 2. After the correction is applied, the measured position can be monitored by reading the *Pos1* register.



Figure 4. Correction Curve

2.3 Zero-Point Offset and Slope Calibration

The goal of the calibration is to ensure that at the mechanical stroke ends, the measured positions are at zero and the maximum position respectively.

The receiver input signals are transformed by the arctan function into a linear position curve called the "spatial angle." The spatial angle is transformed by the calibration process using the zero offset and slope to calculate the calibrated position:

position_cal = (Spa - Zero Offset) × Slope

2.3.1. Zero Offset Correction

The zero offset correction is used for mapping the electric angle to the mechanical angle using the *Zero Offset* term.

Example: It is possible to design a 100° coil and to use a shorter range; e.g., 80°, 90°, 95°. The zero offset correction allows selecting the start point and the end point within this 100° range and allows moving the target in both directions (right to left or left to right).

Important: There is a limit for the designed selected range that depends on various parameters such as geometry, target length, and the maximum slope, which is four.

Figure 5 shows an example of the difference between before and after zero offset correction.



Figure 5. Example of Pos0 Values before and after Zero-Offset Correction

2.3.2. Slope Correction

The slope correction allows mapping the measured angle to the full-scale range for the measurement.

Example: In the graph in Figure 6, the red waveform is the mechanical movement data of the target before slope correction. It is mapped in a range from 0 to 50000_{DEC} . After slope correction, the same mechanical movement of the target is mapped to a range from 0 to 65535_{DEC} as shown by the blue waveform.

The Slope term is a simple multiplication factor.



Figure 6. Slope Correction Example

2.3.3. Coil Offset Compensation

The offset generated from the coils is called the coil offset or amplitude offset. Coil offset is the unwanted additive/subtraction voltage on the receiver's channel. The cause of this offset is the non-uniformity of the magnetic field. Ideally, the voltage measured on both receivers without any target should be zero.

In the ZMID4200, the measurement of the offset is done by reading the internal value of the sine and cosine channel without any metal target near the coils.

This offset can be compensated by values programmed in the EEPROM. The maximum compensation value in the ZMID4200 is $\pm 252_{\text{DEC}}$ for the raw data.

During a complete sweep of the target, the offset on the receiver is seen as a shift of the signal with respect to the x-axis.

Figure 7 shows an example where the shift is by $\boldsymbol{\alpha}.$

The compensation in this example should be

Offset compensation = $\alpha/2$



ZMID4200 / Calibration and Linearization Manual – Analog Output

Figure 7. Offset Compensation

3. Theory for Calibration and Linearization on the Analog Output

The general process follows this sequence:

- 1. Calibration
 - Zero offset
 - Slope
- 2. Linearization of correction points
 - Corr0
 - Corr1
 - ...
 - Corr8

Important: This method of calibration and linearization is valid only for the analog output. The values are expressed in volts.

The linearization function is implemented in the digital domain, and the correction factors are applied at fixed digital points. In order to achieve the linearization, a conversion of the analog output data is required.

If the zero offset is equal to the origin (zero) and the slope is 1, the analog output (volts) is the converted digital raw data.

converted data = spatial value = Pos0 = Pos1

After the analog output measurement, it is possible to calculate the *Spa* value, which is used for calibration and linearization.

Example:

- Zero offset (address 00_{HEX}) = 2400_{HEX} for Linear Output Mode or (address 00_{HEX}) = 0000_{HEX} for Modulo360 Output Mode
- Slope (address 01_{HEX}) = 0400_{HEX}
- VDDE supply = 5V

For this case, the analog output voltage for each measured value is converted using these calculations:

Ratiometric output range = 5% of VDDE to 95% of VDDE = 0.25V to 4.75V

Full-scale voltage output range = 4.75 - 0.25 = 4.5V

This range is mapped to 0 to $(2^{16} - 1)$:

converted data =
$$\frac{(Volt_meas - 0.25) \times (2^{16} - 1)}{4.5 \text{ V}}$$

Where:

Volt_meas is the value measured at the analog output.

3.1 Zero Offset and Slope Calibration

Calibration consists of measurements at the two end points and determination of the zero point offset and slope:

- 1. Measure the actual analog output voltage when the target is in the first position (point A).
- 2. Measure the actual analog output voltage when the target is in the last position (point B).
- 3. Convert the analog output data in the Spa register.

spatial_angle_pt.A is the SPA register value when the target is at point A.

spatial_angle_pt.B is the SPA register value when the target is at point B.

```
If spatial_angle_pt.A < spatial_angle_pt.B
spatial_angle_min = spatial_angle_pt.A
spatial_angle_max = spatial_angle_pt.B
Else
spatial_angle_min = spatial_angle_pt.B
spatial_angle_max = spatial_angle_pt.A</pre>
```

4. Determine the offset of the zero point and save it to memory.

Zero point offset:

offset_value = spatial_angle_min
Map offset_value to register notation:

```
If (offset_value ≤ 2<sup>15</sup>)
   Offset_parameter = 2<sup>13</sup> + 2<sup>10</sup> × [1 - (offset_value/2<sup>15</sup>)]
   else
    offset_parameter = 2<sup>10</sup> × [(offset_value/2<sup>15</sup>) - 1]
Write to EEPROM address:
```

```
address 0x00 = dec2hex [offset_parameter; 4 ]
```

5. Determine the slope correction factor and save it to memory.

Slope:

```
Slope_value = 2<sup>16</sup> /(spatial_angle_max - spatial angle_min)
Slope_parameter = 2<sup>10</sup> × slope_value
Write to EEPROM address:
```

```
address 0x01 = dec2hex[slope_parameter; 4]
```

Optional: Change the slope polarity for the position output

```
offset_value = spatial_angle_max
slope parameter = 2^{12} + 2^{10} \times slope value
```

3.2 Reference Angle Calculation

For the linearization, an ideal reference angle must be generated. The values of an ideal reference angle are defined as an array in the range from 0 to 65535 (*Pos0,* 16 bits). This array contains a given number of elements and a specific step between two adjacent values of the array.

Ideal Data Acquisition: The acquisition of data is done at equidistant time intervals, and the target is moved with constant velocity.

0 0 1 154.5637 2 309.1274 3 463.6911 4 618.2548 5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3254.9651 24 3709.5288 25 3664.0925 26 3640.025 26 3640.025 26 4173.2199	Index	Ideal Pos0 Value
1 154.5637 2 309.1274 3 463.6911 4 618.2548 5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2625.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562	0	0
2 309.1274 3 463.6911 4 618.2548 5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	1	154.5637
3 463.6911 4 618.2548 5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	2	309.1274
4 618.2548 5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	3	463.6911
5 772.8185 6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	4	618.2548
6 927.3822 7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	5	772.8185
7 1081.9459 8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	6	927.3822
8 1236.5096 9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	7	1081.9459
9 1391.0733 10 1545.637 11 1700.2007 12 1854.7644 13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	8	1236.5096
101545.637111700.2007121854.7644132009.3281142163.8918152318.4555162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	9	1391.0733
111700.2007121854.7644132009.3281142163.8918152318.4555162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	10	1545.637
121854.7644132009.3281142163.8918152318.4555162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	11	1700.2007
13 2009.3281 14 2163.8918 15 2318.4555 16 2473.0192 17 2627.5829 18 2782.1466 19 2936.7103 20 3091.274 21 3245.8377 22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	12	1854.7644
142163.8918152318.4555162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	13	2009.3281
152318.4555162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	14	2163.8918
162473.0192172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	15	2318.4555
172627.5829182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	16	2473.0192
182782.1466192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	17	2627.5829
192936.7103203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	18	2782.1466
203091.274213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	19	2936.7103
213245.8377223400.4014233554.9651243709.5288253864.0925264018.6562274173.2199	20	3091.274
22 3400.4014 23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	21	3245.8377
23 3554.9651 24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	22	3400.4014
24 3709.5288 25 3864.0925 26 4018.6562 27 4173.2199	23	3554.9651
25 3864.0925 26 4018.6562 27 4173.2199	24	3709.5288
26 4018.6562 27 4173.2199	25	3864.0925
27 4173.2199	26	4018.6562
	27	4173.2199

Table 2. Example of Ideal Data

Definitions:

Step_value_Pos0: Step value between two adjacent values.

Pos0_ideal_elem_nr: The number of elements present in the ideal reference angle.

Spat_ele_nr: The number of samples that are read from the *Spatialangle* register during a complete sweep of the target.

Pos0_ideal_elem_nr is equal to *Spat_ele_nr*.

Step_value_Pos0 is calculated as Step_value_Pos0 = 65535 / Pos0_ideal_elem_nr

Ideal_Pos0_Value is an array that is populated as follows:

```
index = 0
While (index < Pos0_ideal_elem_nr)
{
    Ideal_Pos0_Value[index] = index × Step_value_Pos0
    Index ++
}</pre>
```

3.3 Determining the Correction Factor for Linearization

Table 2 provides an example of the calculations for correction factors when Pos0_ideal_elem_nr is 383.

In Table 3, the "OutputCalPOS0" column contains the analog output converted value from a complete sweep of the target.

The "Difference" column value is calculated as *Ideal_pos0_Value[Index_calc] – OutputCalPOS0[Index_calc]*. For the "Difference/32" column, 32 is a scaling factor inherent to the ZMID4200.

Index_calc	OutputCalPOS0	Ideal_pos0_Value	Difference	Difference/32	Difference/32 [Hexadecimal]
0	3277	3245			
1	3289	3400			
32	6775	8191.875	1417	44.26	Corr1 = 2C
85	14094	16383.75	2290	71.553	Corr2 = 47
381	62172				
382	62258				

Table 3. Correction Factor Calculation

The correction factor and the respective fixed point values are given in Table 1.

Linearization algorithm for Corr0 to Corr8:

Corr1 factor:

- 1. In the *Ideal_pos0_Value* array, find the closest value to 8192. (See Table 3.)
- 2. Calculate the difference between the found value and the value of the array *OutputCalPOS0* that has the same index.
- 3. *Corr1* = difference / 32
- 4. Convert the data to hexadecimal and write it to EEPROM.

Repeat the four steps for each remaining correction factor (Corr0, Corr2, Corr3, ... Corr8).

Example for Corr2:

- 1. In the *Ideal_Pos0_Value* array, the element with the value 16384 is found and the *Index_calc* = 85 (see Table 3.)
- 2. In Table 3, the value of the array *OutputCalPOS0* at index = 85 is equal to 14094.

3. The difference between these two values divided by 32 is the correction factor for *Corr2*.

(16383.75 – 14094) / 32 = 71.553

4. Convert the data to hexadecimal and write it to EEPROM.

4. Clamping Analog Output for the ZMID4200

The ZMID4200 has a ratiometric analog output; i.e., the span of the electrical output signal is proportional to the excitation voltage applied, which depends on the supply voltage. The output is expressed in percentage with respect to VDDE. The maximum and minimum for the range of the output with respect to VDDE can be varied by clamping; i.e., maintaining the upper and lower limits of the electrical output signal at prescribed values.

4.1 The Relationship between the Internal Value and the Output

The internal DAC of the ZMID4200 converts the internal register values (*Pos1*) into analog output data. Only 90% of VDDE is used for the analog output, so the full-scale (FS) range of the internal values is mapped to 90% of the VDDE range for the output.

The minimum value for the *Pos1* register is zero, and the maximum is $(2^{16} - 1)$.

Note: The minimum and maximum output limits will be respectively 5% to 95% of VDDE when there is no clamping. The output values are proportional to the internal values. When the internal range is compressed to a smaller range, the output range will also be decreased.

Clamping allows varying the output range without changing the target travel.



Note: See section 4.2.2 for a description of this type of clamping

Figure 8. Pos1 Output Mapped to 5% to 95% VDDE (No Clamping)

Clamping is used in applications that require an output range that is different from the default of 5% to 95% VDDE. An example is shown in Figure 9. The decision to use clamping should be guided by the customer requirements or the electrical limits of the application/sensor.



Note: See section 4.2.2 for a description of this type of clamping.

Figure 9. Clamping in an Output of 20% to 80%VDDE and Clamping in Pos1 to 16.667% to 83.33% FS

4.2 Applying the Clamping Process

Clamping in the ZMID4200 is implemented by two different processes. Both are mandatory in the following order for correct clamping.

- 1. Calibration process by tuning the calibration parameters (see section 4.2.1)
- 2. Register clamping by configuring bits in EEPROM address 02_{HEX} (see section 4.2.2)

4.2.1. Calibration Process

The clamping by the calibration process is calculated based on the correlation between the internal value (*Pos1*) and the analog output. The *Pos1* register value represents the measured position as digital-format raw data.

The calibration process directly affects the internal raw data and indirectly affects the output clamping by limiting the minimum and maximum data in the *Pos1* register, which will also limit the output range.

The process for clamping by calibration determines a slope and zero offset that result in a specified minimum and maximum output for a given target movement.

4.2.2. Register Clamping

Register clamping can limit the output based on the VDDE reference regardless of where the target is positioned or how the slope and zero offset are defined. Register clamping uses only the VDDE of the ZMID4200 as the reference, without any link to the internal values.

An example of register clamping is shown In Figure 8 where the 0% to 100 % FS range for *Pos1* is correlated to 5% to 95% of the output. Another clamping example is given Figure 9 where the 16.667% to 83.33 % FS range for *Pos1* is correlated to 20% to 80% of the output.

4.3 **Proper Clamping Requirements**

For proper clamping, both the calibration and register clamping must be applied. Clamping only by the calibration process is inadequate because whenever the target is moved out of the operation range (start to end), the calibration mapping will no longer be valid. The output value will exceed the limit defined by the calibration process mapping.

Clamping only by register clamping will decrease not only the output range but the measurement range as well.

The clamping requirements for the analog output can be satisfied only by applying the two different clamping methods simultaneously in the following sequence.

- 1. Clamping by the calibration process:
 - a. Clamp_low_calib is defined by the calibration process
 - b. Clamp_high_calib is defined by the calibration process
- 2. Clamping by register configuration:
 - a. Reg_low_value: Value to be written in EEPROM register 02HEX
 - b. Reg_high_value: Value to be written in EEPROM register 02_{HEX}

The calculations for both these processes are automatically performed by the OneStepCalibration algorithm.

4.4 Clamping via Calibration

In the OneStepCalibration algorithm, the clamping is defined as follows:

Clamp_low = Clamp_low_value O % O VDDE

Clamp_low_value (no units)

Clamp_high = Clamp_high_value O % O VDDE

Clamp_high_value (no units)

The inputs for the *OneStepCalibration* algorithm are *Clamp_low_value* and *Clamp_high_value*. The outputs of the algorithm are the calibration parameters, Slope and Zero Offset.

The movement range of the target (start to end point) is verified as Clamp_low_value to Clamp_high_value.

Example:

VDDE = 5V

Clamp_low = 10% VDDE = 0.5 Volt

When the target position is at the start point, the output value will be 0.5 volt.

Clamp_high = 90% VDDE = 4.5 Volt

When the target position is at the end point the output, value will be 4.5 volt.

4.5 Clamping via Register Clamping

Clamping using the register is just a clamp of the output with respect to VDDE.

For register clamping, the inputs for the *OneStepCalibration* algorithm are *Clamp_low_value* and *Clamp_high_value*. The outputs of the algorithm are *Reg_low_value* and *Reg_high_value*.

4.5.1. Register Clamping Low

The user defines the clamping with respect to VDDE.

Clamp_low = Clamp_low_value O % O VDDE

Clamp_low_value = input value (no units).

 $Reg_low_value = floor(\frac{Clamp_low_value - 5}{0.9})$ (in decimal)

Where the function "floor" rounds the number to the next smaller integer.

Reg_low_value must be written to bits [7:0] in EEPROM register 02_{HEX}.

4.5.2. Register Clamping High

The user defines the clamping with respect to VDDE.

Clamp_high = *Clamp_high_value* O % O *VDDE* (This is the same for both register clamping and calibration mapping.)

Clamp_high_value = input value (no units).

 $Reg_high_value = floor(\frac{95 - Clamp_high_value}{0.9})$ (in decimal)

Reg_high_value must be written to the bits [15:8] in EEPROM register 02HEX.

4.6 Calibration Clamping vs. Register Clamping

Important: Calibration clamping and register clamping have a different resolution step.

Register clamping has a clamping step of 0.9% of VDDE.

The step value with register clamping can be calculated as follows:

 $Clamp_low_reg = 5\% \square VDDE + 0.9\% \square VDDE \square Reg_low_value$ (The low clamping output expressed in volts when Reg_low_value is written in bits [7:0] in EPROM register 02_{HEX} (integer).)

 $Clamp_high_reg = 95\% \square VDDE - 0.9\% \square VDDE \square Reg_high_value$ (The high clamping output expressed in volts when Reg_high_value is written in bits[15:8] in EPROM register 02_{HEX} (integer).)

Calibration clamping has about x10 more resolution than register clamping and this leads to an imperfect match for these two types of calibration.

Example:

VDDE = 5VClamp_low = 10% VDDE = 0.5VFrom specificationClamp_low_value = 10DefinitionReg_low_value = 5Calculated by the equation given in section 4.5.1Clamp_low_reg = 0.475VCalculated by the equation above

The difference between the calibration clamping and register clamping:

Difference = $Clamp_low - Clamp_low_reg = 0.5 - 0.475 = 0.025V$ (see Figure 10)

The tolerance is 25mV, which is 0.555% FS where FS = 4.5V.



Note: In the following graph, the blue line indicates Pos0 data; the red line indicates Pos1 data; and the dashed line is the ideal measurement.



5. Requirements for Measurement of SPA and Analog Output When Using the *OneStepCalibration* Algorithm

Measuring the position during one sweep of the target is necessary for calibration and linearization. There are requirements for a correct measurement process.

The calibration and linearization process requires a mechanical test bench for executing a controlled and accurate movement of the target. The algorithm behind the process is implemented under the hypothesis of an ideal mechanical system. The quality of the calibration and linearization is directly related to the quality of the reference mechanical movement. The nonlinearity in the measured position is only associated with the sensor.

In practice, a motor/step motor is needed to execute the movement of the target under specific conditions including the following:

- 1. A specific air gap (distance between the coils and target)
- 2. Linear movement
- 3. Rotary movement

Synchronization: The acquisition of the SPA, analog voltage, and the target movement should be synchronized.

The starting point and end point are defined by the application.

The target should move from the starting point to the end point. After calibration, the start point will be the zero position and the end point will be the full scale position.

The measured, electrical data is linearly mapped to the mechanical movement.

An increase in the target travel range will decrease the resolution, as the same electrical output range will be mapped to a bigger movement range of the target.

In practice, there are two alternative ways to accomplish the measurement needed for calibration and linearization.

- 1. Synchronization between the target movement and the acquisition: The target should move in equidistant steps, and the acquisition should occur as soon as the target is stopped between each movement step.
- 2. Moving the target with a constant speed from the start point to the end and simultaneously performing the data acquisition with a constant speed. The acquired data should be considered linear to the target movement.

These two different acquisition methods are not dependent on the type of the acquisition output.

The number of acquisitioned samples in one target sweep should be about 300. Note that this is an approximate number; a larger number will result in better performance of the calibration and linearization. The GUI accepts a maximum of 1500 samples when uploading the .csv file that is used to transfer measurement data to the GUI. The calibration and linearization will proceed automatically.

5.1 **EEPROM Configuration before Performing the Measurement**

Important: General configuration is needed before the measurement including for the gain stage, post calibration, amplitude offset, and output mode.

Gain Stage

For a specific air gap, which is defined by the application, read the CORDIC Magnitude register when the target is on the top of the coils between the start point and the end point. Theoretically, the magnitude will be constant during the sweep of the target as long as the target is on the top of the receiver coils.

The optimal value should be 7000 to 10000 at room temperature. Define the gain stage to an appropriate stage to satisfy the optimal CORDIC Magnitude. (The range of the gain stage is 1 to 12)

Post Calibration

Strong recommendation: Use post calibration; i.e., apply the linearization after calibration.

Amplitude Offset or Coil Offset

The offset value should be zero if an ideal coil has been designed. In practice there is always some offset, and this can be compensated by a bit configuration in EEPROM.

Recommendation: Measure the offset by reading the internal value (sine and cosine channel) without the target after the gain stage has been defined.

Output Mode

There are the following two output mode:

- Linear Output mode: applicable in arc and linear sensors. Possible jumps in the spatial angle must be eliminated by a bit configuration change.
- Mode 360: only applicable in rotary 360-degree movement or with multi-period sensors. Do not use it for an
 angle narrower than 360°. If there is any mechanical tolerance in the target position at the start point or at the
 end point, a big jump in output from minimum to maximum will cause an error of 100%.

The Clamping Coefficient Configuration before Measuring

The clamping coefficient configuration should be zero before the measurement when the analog output is used. This has no influence on the internal value of the SPA.

The Calibration and Linearization Coefficient Configuration before Measuring

OWI: When the SPA register is read, ignore the bit configuration.

6. OneStepCalibration Automatic Calibration and Linearization

OneStepCalibration is a fast algorithm for calculating the calibration and linearization coefficient. The algorithm is very easily implemented.

For input, *OneStepCalibration* needs the spatial angle measurement during one sweep of the target and some basic configuration values including sign slope, output mode, reverse slope, and clamping output.



Figure 11. Inputs and Outputs for OneStepCalibration

The same algorithm can be used when the measurement data is analog.

The OneStepCalibration algorithm should be used for performance validation and for end-of-line calibration.



Figure 12. General Flow Diagram for Using Internal Values for Calibration and Linearization



Figure 13. Flow Diagram When the Analog Output is used for Calibration and the Linearization

7. Validation: Error Calculation after Calibration and Linearization

After calibration and linearization, another measurement is needed to validate that the overall process has been performed correctly. The measurement should be performed in the same manner with the same output used for the calibration and linearization measurement. Any change in the target position (air gap, start point, end point) in this procedure could lead to an incorrect validation.

Once the measurement has been performed and the data is available, the error can be calculated as follows:

Elem = 0 :1: ($Nr_elem - 1$) Matlab code

Where Nr_elem is the number of the position acquisition during the sweep of the target.

Difference between Pos1 and the ideal line mapped to the FS in percentage:

FNL_elm = 100 O (list_Pos1[elem] - Ideal_list[elem]) / list_Pos1[Nr_elem - 1] //

Where:

FNL is the final nonlinearity.

list_Pos1[elem] is the array with data from reading the *Pos1* register during the sweep of the target.

Ideal_list[*elem*] is an array with the same number of elements as *Pos1*; all the elements are part of the ideal straight line that is defined by the first element of the Pos1 and last element of the Pos1.

For analog the procedure is the same.

In the respective formula, use the output value instead of Pos1[elem].

Difference between Analog value and the Ideal line mapped to the FS in percentage

FNL_elm = 100 O (list_Analog[elem] – Ideal_list[elem]) / list_Analog[Nr_elem – 1] //

8. Revision History

Revision	Date	Description
1.0	Jul 21, 2021	Initial release.

Notice

- 1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation or any other use of the circuits, software, and information in the design of your product or system. Renesas Electronics disclaims any and all liability for any losses and damages incurred by you or third parties arising from the use of these circuits, software, or information.
- Renesas Electronics hereby expressly disclaims any warranties against and liability for infringement or any other claims involving patents, copyrights, or other intellectual property rights of third parties, by or arising from the use of Renesas Electronics products or technical information described in this document, including but not limited to, the product data, drawings, charts, programs, algorithms, and application examples.
- 3. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
- 4. You shall be responsible for determining what licenses are required from any third parties, and obtaining such licenses for the lawful import, export, manufacture, sales, utilization, distribution or other disposal of any products incorporating Renesas Electronics products, if required.
- 5. You shall not alter, modify, copy, or reverse engineer any Renesas Electronics product, whether in whole or in part. Renesas Electronics disclaims any and all liability for any losses or damages incurred by you or third parties arising from such alteration, modification, copying or reverse engineering.
- 6. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The intended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.
 - "Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; industrial robots; etc.

"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control (traffic lights); large-scale communication equipment; key financial terminal systems; safety control equipment; etc.

Unless expressly designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not intended or authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems; surgical implantations; etc.), or may cause serious property damage (space system; undersea repeaters; nuclear power control systems; aircraft control systems; key plant systems; military equipment; etc.). Renesas Electronics disclaims any and all liability for any damages or losses incurred by you or any third parties arising from the use of any Renesas Electronics product that is inconsistent with any Renesas Electronics data sheet, user's manual or other Renesas Electronics document.

- 7. No semiconductor product is absolutely secure. Notwithstanding any security measures or features that may be implemented in Renesas Electronics hardware or software products, Renesas Electronics shall have absolutely no liability arising out of any vulnerability or security breach, including but not limited to any unauthorized access to or use of a Renesas Electronics product or a system that uses a Renesas Electronics product. RENESAS ELECTRONICS DOES NOT WARRANT OR GUARANTEE THAT RENESAS ELECTRONICS PRODUCTS, OR ANY SYSTEMS CREATED USING RENESAS ELECTRONICS PRODUCTS WILL BE INVULNERABLE OR FREE FROM CORRUPTION, ATTACK, VIRUSES, INTERFERENCE, HACKING, DATA LOSS OR THEFT, OR OTHER SECURITY INTRUSION ("Vulnerability Issues"). RENESAS ELECTRONICS DISCLAIMS ANY AND ALL RESPONSIBILITY OR LIABILITY ARISING FROM OR RELATED TO ANY VULNERABILITY ISSUES. FURTHERMORE, TO THE EXTENT PERMITTED BY APPLICABLE LAW, RENESAS ELECTRONICS DISCLAIMS ANY AND ALL WARRANTIES, EXPRESS OR IMPLIED, WITH RESPECT TO THIS DOCUMENT AND ANY RELATED OR ACCOMPANYING SOFTWARE OR HARDWARE, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY, OR FITNESS FOR A PARTICULAR PURPOSE.
- 8. When using Renesas Electronics products, refer to the latest product information (data sheets, user's manuals, application notes, "General Notes for Handling and Using Semiconductor Devices" in the reliability handbook, etc.), and ensure that usage conditions are within the ranges specified by Renesas Electronics with respect to maximum ratings, operating power supply voltage range, heat dissipation characteristics, installation, etc. Renesas Electronics disclaims any and all liability for any malfunctions, failure or accident arising out of the use of Renesas Electronics products outside of such specified ranges.
- 9. Although Renesas Electronics endeavors to improve the quality and reliability of Renesas Electronics products, semiconductor products have specific characteristics, such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Unless designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not subject to radiation resistance design. You are responsible for implementing safety measures to guard against the possibility of bodily injury, injury or damage caused by fire, and/or danger to the public in the event of a failure or malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult and impractical, you are responsible for systems manufactured by you.
- 10. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. You are responsible for carefully and sufficiently investigating applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive, and using Renesas Electronics products in compliance with all these applicable laws and regulations. Renesas Electronics disclaims any and all liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
- 11. Renesas Electronics products and technologies shall not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You shall comply with any applicable export control laws and regulations promulgated and administered by the governments of any countries asserting jurisdiction over the parties or transactions.
- 12. It is the responsibility of the buyer or distributor of Renesas Electronics products, or any other party who distributes, disposes of, or otherwise sells or transfers the product to a third party, to notify such third party in advance of the contents and conditions set forth in this document.
- 13. This document shall not be reprinted, reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
- 14. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products.
- (Note1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its directly or indirectly controlled subsidiaries.
- (Note2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

(Disclaimer Rev.5.0-1 October 2020)

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.