

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan
Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RA*-A0149A/E	Rev.	1.00
Title	Note about the interruption during the transition to low power modes		Information Category	Technical Notification		
Applicable Product	RA0E1, RA0E2, RA2L1, RA2L2, RA2E1, RA2E2, RA2E3, RA2A1, RA2A2 Group	Lot No.	Reference Document	Refer table at the end of this document		
		All				

Corrections are made to the figures and tables in the user's manual hardware as shown in 1 and 2 below.

If the software meets the applicable condition listed in 4 below, you may not be able to enter the intended low power mode and transit to unintended states described in 4 below.

If the unintended states described in the following 4 notes cannot be tolerated, use the following 5 workaround.


Contents

1. Correction of the Figure "Mode transitions"	2
2. Correction of the table "Operating conditions of each low power mode"	6
3. Notes when transition to low power modes by Sleep-on-exit.	7
4. Applicable condition and notes	7
5. Workaround	8


1. Correction of the Figure “Mode transitions”

1) Figure 9.1 of RA0E1 and RA0E2 groups

Before correction




After correction




2) Figure 10.1 of RA2L1, RA2L2, RA2E1, RA2E2 and RA2E3 groups

Before correction




After correction




3) Figure 11.1 of RA2A1 group

Before correction




After correction




4) Figure 11.1 of RA2A2 group

Before correction



After correction



2. Correction of the table “Operating conditions of each low power mode”

Table 9.2 of the RA0E1 and RA0E2 groups, Table 10.2 of the RA2L1, RA2L2, RA2E1, RA2E2 and RA2E3 groups, And table 11.2 of the RA2A1 and RA2A2 groups.

Before correction

Parameter	Sleep mode	Software Standby mode	Snooze mode
Transition condition	WFI instruction while SBYCR.SSBY = 0	WFI instruction while SBYCR.SSBY = 1	Snooze request trigger in Software Standby mode. SNZCR.SNZE = 1
State after cancellation by an interrupt	Program execution state (interrupt processing)	Program execution state (interrupt processing)	Program execution state (interrupt processing)

After correction

Parameter	Sleep mode	Software Standby mode	Snooze mode
Transition condition	When [Condition 1] or [Condition 2] while SBYCR.SSBY=0 [Condition 1] <ul style="list-style-type: none"> • WFI instruction • A valid interrupt request(*1) cannot be accepted to CPU. (including a transition from the time WFI instruction is executed to the time the transition to Sleep mode is completed) [Term 2] <ul style="list-style-type: none"> • SCR.SLEEPONEXIT=1 • Complete execution of all exception handlers • A valid interrupt request(*1) cannot be accepted to CPU. (including a transition from the time WFI instruction is executed to the time the transition to Sleep mode is completed) 	When [Condition 1] or [Condition 2] while SBYCR.SSBY=1 [Condition 1] <ul style="list-style-type: none"> • WFI instruction • A valid interrupt request(*1) cannot be accepted to CPU. (including a transition from the time WFI instruction is executed to the time the transition to Software Standby mode is completed) [Term 2] <ul style="list-style-type: none"> • SCR.SLEEPONEXIT=1 • Complete execution of all exception handlers • A valid interrupt request(*1) cannot be accepted to CPU. (including a transition from the time WFI instruction is executed to the time the transition to Software Standby mode is completed) 	Snooze request trigger in Software Standby mode. SNZCR.SNZE = 1
State after cancellation by an interrupt	Program execution state	Program execution state	Program execution state

(*1) Valid interrupt requests are any interrupt/exception that are not masked by the priority level of current exception and the priority level set by BASEPRI. In addition, if the interrupt request is based on IELSRn, the interrupt must be enabled by NVIC_ISERN.

3. Notes when transition to low power modes by Sleep-on-exit.

There are 2 ways to transition to low power modes. One is WFI instruction and the other is Sleep-on-exit. When Sleep-on-exit is used for transition to low power modes, WFI instruction comments written in User's Manual Hardware is applicable to Sleep-on-exit.

4. Applicable condition and notes

Applicable products: RA2L1, RA2L2, RA2E1, RA2E2, RA2E3, RA2A1 and RA2A2 groups (RA0E1 and RA0E2 groups are not applicable)

[Applicable condition]

Transition to Software Standby mode is started by a trigger (WFI instruction or SLEEPONEXIT) with SBYCR.SSBY=1 set to use Software Standby or Snooze mode.

During the specified interval (ICLK 2cycle) of transitioning to Software Standby mode, one of the following interrupt requests that is not an interrupt source to return from Software Standby mode is accepted by CPU.

1) SysTick interrupt

- Exception number 15 of Interrupt vector table .

2) Maskable interrupt requests that are not interrupt source to return from Software Standby mode (all of the following are applicable)

- By WUPEN in exception numbers 16 to 83 in the interrupt vector table those not permitted to return from Software Standby mode
- Interrupt requests are enabled by Interrupt Set-Enable Register (NVIC_ISERn).

3) Non-maskable interrupt request triggered by the following sources

- SRAM parity error
- SRAM ECC failure (RA2L2 and RA2E1/2/3 groups are not applicable)
- Bus master MPU error
- Bus slave MPU error

[Notes]

If the above conditions are met, the MCU will transit to following unintended states.

These unintended states can be resolved by a reset or returning to Normal mode with an interrupt request of an interrupt source to return from Software Standby mode.

Adapt a workaround if these unintended states are not acceptable.

1) When transitioning to Software Standby mode (SBYCR.SSBY=1, SNZCR.SNZE=0)

Only CPU clock is stopped, and the remaining clocks continue to operate as they were prior to transitioning Software Standby mode.

- As before the transition to Software Standby mode is started, depending on the setting, timer or other peripherals continue to

operate, and an interrupt request related to the peripheral is generated.

- Because the IWDT and WDT clock-stop function is disabled, a reset or an interrupt for the IWDT and WDT is generated depending on the settings before starting the transition to Software Standby mode.
- Interrupt requests are held in IR flag (IELSRn, DELSRn).

2) When transitioning to Snooze mode (SBYCR.SSBY=1, SNZCR.SNZE=1)

The transition to Snooze mode is not possible, and the states shown in “1) When transitioning to Software Standby mode” is continued.

To return to Normal mode by an interrupt source (SELSR0) from Snooze mode depends on whether the interrupt request (SELSR0) to returning from Snooze mode can be generated while DTC operation is disabled.

If DTC operation is disabled (SNZCR.SNZDTCEN=0) in Snooze mode, Normal mode can be returned because an interrupt source for the interrupt source (SELSR0) to return from Snooze mode can be generated.

If DTC operation is enabled (SNZCR.SNZDTCEN=1) in Snooze mode, the Normal mode cannot be returned because an interrupt request for the interrupt source (SELSR0) to return from Snooze mode cannot be generated.

5. Workaround

Applicable products: RA2L1, RA2L2, RA2E1, RA2E2, RA2E3, RA2A1 and RA2A2 groups (RA0E1 and RA0E2 groups are not applicable)

To avoid the unintended states described above, apply the following before the terms for transition to Software Standby mode or Snooze mode are met: (For the setting procedure, see "Setting Procedure for Transition to Software Standby Mode or Snooze Mode")

1) Disable SysTick interrupt requests.

Exception number 15 of Interrupt vector table

2) Disable maskable interrupt requests that are not interrupt sources to return from Software Standby mode.

Exception number 16~83 of Interrupt vector table that WUPEN does not allow to return from Software Standby mode

3) Stop access from the bus master other than the CPU so that the non-maskable interrupt is not triggered by the following sources.

SRAM parity error

SRAM ECC failure (RA2L2 and RA2E1/2/3 groups are not applicable)

Bus master MPU error

Bus slave MPU error

Setting Procedure for Transition to Software Standby Mode or Snooze Mode

This section describes procedures for avoiding unintended states.

The handling of interrupt requests after returning from Software Standby or Snooze mode varies depending on the method used to disable the maskable interrupt request. Either one or the other should be applied.

Step A) Disable maskable interrupt request acceptance. (RA2A2 group is not applicable)

Any interrupt request that occurs while interrupt request acceptance is disabled is discarded.

Before transitioning to Software Standby mode or Snooze mode

- Step1: Stop the bus access from the bus master other than CPU. (*1)
- Step2: Disable the SysTick interrupt request. (*2)
- Step3: Clear IELSRn in ICU to disable acceptance of maskable interrupt requests that are not interrupt sources to return from Software Standby mode.
- Step4: Read IELSRn in ICU to confirm that IELSRn in ICU has been cleared.
- Step5: Transition to Software Standby mode (WFI instruction, SLEEPONEXIT)

After returning from Software Standby mode or Snooze mode

- Step6: Enable the SysTick interrupt request.
- Step7: Set IELSRn in ICU to enable acceptance of maskable interrupt requests that are not interrupt sources to return from Software Standby mode.
- Step8: Enable bus access from bus masters other than CPU.

Step B) Disable the maskable interrupt request

The interrupt request generated while the interrupt request is disabled is retained in IELSRn.IR flag. Therefore, after returning from Software Standby or Snooze mode and enabling the maskable interrupt, it is possible to process the interrupt.

Before transitioning to Software Standby or Snooze mode

- Step1: Stop the bus access from the bus master other than CPU. (*1)
- Step2: Disable the SysTick interrupt request. (*2)
- Step3: Write 1 to the corresponding bit in NVIC_ICERn in CPU to disable maskable interrupt requests that are not interrupt sources to return from Software Standby mode.
- Step4: Execute Data Synchronization Barrier (DSB) instruction.
- Step5: Transition Software Standby mode (WFI instruction, SLEEPONEXIT)

After returning from Software Standby or Snooze mode

- Step6: Enable the SysTick interrupt request.
- Step7: Write 1 to the corresponding bit in NVIC_ISERn in CPU to enable maskable interrupt requests that are not interrupt sources to return from Software Standby mode.
- Step8: Enable bus access from bus masters other than CPU.

*1: SRAM parity error interrupt, SRAM ECC error interrupt, Bus master MPU error interrupt or Bus slave MPU error interrupt is enabled as a non-maskable interrupt.

*2: Disabling a SysTick interrupt request may cause SysTick interrupt request to be delayed by one cycle of SysTick timer without generating the latest SysTick interrupt request.

Reference for each product table number, register name, mode, error name.

1. Interrupt vector table is as follows.

Table 11.3 shows the interrupt vector table for RA0E1 and RA0E2 groups.

Table 12.3 shows the interrupt vector table for RA2L1, RA2L2, RA2E1, RA2E2 and RA2E3 groups.

Table 13.3 shows the interrupt vector table for RA2A1 and RA2A2 groups.

2. The maximum exception number in the interrupt vector table is as follows:

79 for RA0E1 and RA0E2 groups.

47 for RA2L1, RA2L2, RA2E1, RA2E2, RA2E3 and RA2A1 groups.

83 for RA2A2 group.

3. WUPEN register name for each product is as follows.

WUPEN is used for RA2L1, RA2E1, RA2E2, RA2E3 and RA2A1 groups.

WUPEN/2 is used for RA2L2 group.

WUPEN0/1 is used for RA2A2 group.

Related Documentation

Product	Document Name
RA0E1 Group	Renesas RA0E1 Group User's Manual: Hardware Rev. 1.10
RA0E2 Group	Renesas RA0E2 Group User's Manual: Hardware Rev. 1.00
RA2L1 Group	Renesas RA2L1 Group User's Manual: Hardware Rev. 1.50
RA2L2 Group	Renesas RA2L2 Group User's Manual: Hardware Rev. 1.10
RA2E1 Group	Renesas RA2E1 Group User's Manual: Hardware Rev. 1.50
RA2E2 Group	Renesas RA2E2 Group User's Manual: Hardware Rev. 1.40
RA2E3 Group	Renesas RA2E3 Group User's Manual: Hardware Rev. 1.20
RA2A1 Group	Renesas RA2A1 Group User's Manual: Hardware Rev. 1.10
RA2A2 Group	Renesas RA2A2 Group User's Manual: Hardware Rev. 1.20