

## Microcontroller Technical Information

QB-Programmer Programming GUI for QB-MINI2  Usage Restrictions		Document No.	ZBG-CD-09-0065	1/2
		Date issued	December 24, 2009	
		Issued by	Development Tool Solution Group Multipurpose Microcomputer Systems Division Microcomputer Operations Unit NEC Electronics Corporation	
Related documents	QB-Programmer Operation User's Manual: U18527EJ1V0UM00	Notification classification	√	Usage restriction
				Upgrade
				Document modification
				Other notification

### 1. Affected product

Product	Outline	Affected Version
QB-Programmer	Programming GUI for QB-MINI2	V3.00 or earlier

Version confirmation:

- The version is displayed in the **Programmer** area in the programmer parameter window in the main window.

### 2. New item

A new restriction (No. 5) has been added. See the attachment for details.

### 3. Workaround

See the document for details.

### 4. Modification schedule

Products from which the above restriction (No. 5) is removed will be posted on the Development Tools Download webpage on January 13, 2010 (QB-Programmer V3.10).

\* Note that this schedule is subject to change without notice. For the detailed release schedule of modified products, contact an NEC Electronics sales representative.

### 5. List of restrictions

See the attachment.

## 6. Document revision history

## Programming GUI for QB-MINI2 QB-Programmer - Usage Restrictions

Document Number	Issued on	Description
ZBG-CD-06-0084	September 21, 2006	Newly created. Addition of new restriction (No. 6)
ZBG-CD-07-0006	January 18, 2007	Addition of new restrictions (No. 7 to No. 9) Addition of new specification (No. 10)
ZBG-CD-07-0035	June 4, 2007	Division of Product History into two sections: <i>Additions and changes to specification</i> , and <i>Restrictions</i> . Addition of new specification (No. 7)
ZBG-CD-09-0065	December 24, 2009	Addition of new restriction (No. 5) Deletion of <i>Additions and changes to specification</i> from the attachment

## Restrictions on Using QB-Programmer

### 1. Product Version

Item No.	QB-Programmer Version	MINICUBE2 Firmware Version	Remark
<1>	V1.00	V1.00 or later and earlier than V4.00	
<2>	V2.00	V4.00 or later	
<3>	V2.10	V4.00 or later	
<4>	V2.20	V4.03 or later	
<5>	V2.21	V4.03 or later	
<6>	V2.22	V4.03 or later	
<7>	V2.24	V4.03 or later	
<8>	V3.00	V4.07 or later	
<9>	V3.10	V5.00 or later	

### 2. Restrictions

#### 2.1 Restrictions list

No.	Restrictions	Item Number								
		<1>	<2>	<3>	<4>	<5>	<6>	<7>	<8>	<9>
1	Restriction on signature verification	○	×	○	○	○	○	○	○	○
2	Restriction on executing the <b>Read</b> command	–	×	×	○	○	○	○	○	○
3	Restriction on using UART communication with a high baud rate	○	×	×	○	○	○	○	○	○
4	Restriction on using PG-Programmer with a 78K0R/Kx3 microcontroller	–	×	×	○	○	○	○	○	○
5	Restriction on aborting QB-Programmer when a specific HEX file is loaded	×	×	×	×	×	×	×	×	○

–: Not relevant, ×: Applicable, ○: Corrected

## 2.2 Restrictions details

### No. 1 Restriction on signature verification

#### Description:

When the internal flash memory (using any kind of commands, such as the **E.P.V.** command) is manipulated with any one of the following 30 devices, signature verification might be invalid. In this case, the error message `E2004: Communication failure or timeout!` is output. If the signature verification is completed normally, data is written correctly.

#### Affected devices:

V850ES/Jx2:  $\mu$ PD70F3723,  $\mu$ PD70F3721,  $\mu$ PD70F3720,  $\mu$ PD70F3718,  $\mu$ PD70F3716,  $\mu$ PD70F3715

V850ES/IE2:  $\mu$ PD70F3713

V850ES/Hx2:  $\mu$ PD70F3711,  $\mu$ PD70F3709,  $\mu$ PD70F3706,  $\mu$ PD70F3703,  $\mu$ PD70F3702,  $\mu$ PD70F3700

V850ES/Fx2:  $\mu$ PD70F3238,  $\mu$ PD70F3232

78K0/Kx1+:  $\mu$ PD78F0102H,  $\mu$ PD78F0101H,  $\mu$ PD78F0113H,  $\mu$ PD78F0112H,  $\mu$ PD78F0123H,  
 $\mu$ PD78F0122H,  $\mu$ PD78F0136H,  $\mu$ PD78F0134H,  $\mu$ PD78F0133H,  $\mu$ PD78F0132H

78K0/Fx1+:  $\mu$ PD78F0878,  $\mu$ PD78F0877,  $\mu$ PD78F0874,  $\mu$ PD78F0872,  $\mu$ PD78F0871

#### Workaround:

Use QB-Programmer V1.00 as a temporary workaround.

#### Action:

This issue has been corrected in QB-Programmer V2.10 and later.

### No. 2 Restriction on executing the **Read** command

#### Description:

If the **Read** command is executed for one of the devices below (as of December 1, 2006) under the conditions that the communication mode is SIO-H/S and the main clock frequency is 10 MHz or lower, the invalid error message `E0001: USB host connection failed.` might be output.

If the command execution is completed normally, it means that the **Read** command was executed correctly.

Affected devices: V850ES/Kx1+, V850ES/Kx2, V850ES/Sx3, V850ES/Fx3.

#### Workaround:

There is no workaround.

#### Action:

This issue has been corrected in QB-Programmer V2.20 and later and MINICUBE2 firmware V4.03 and later.

### No. 3 Restriction on using UART communication with a high baud rate

#### Description:

When the internal flash memory (using any kind of commands, such as the **E.P.V.** command) is manipulated via UART communication with a communication speed higher than 115,200 bps, the error message `E2004: Communication failure or timeout.` might be output.

If the command execution is completed, it means that the command was executed correctly.

#### Workaround:

There is no workaround.

#### Action:

This issue has been corrected in MINICUBE2 firmware V4.03 and later.

### No. 4 Restriction on using PG-Programmer with a 78K0R/Kx3 microcontroller

#### Description:

When the internal flash memory (using any kind of commands, such as the **E.P.V.** command) is manipulated with one of the following 78K0R/Kx3 devices of Ver. 2.1 or earlier, the error message `E2002:No response from Target Device. (Reset)` is output.

Affected devices:  $\mu$ PD78F1142,  $\mu$ PD78F1146,  $\mu$ PD78F1156,  $\mu$ PD78F1164,  $\mu$ PD78F1165,  $\mu$ PD78F1166

#### Workaround:

There is no workaround.

#### Action:

This issue has been corrected in QB-Programmer V2.20 and later.

### No. 5 Restriction on aborting QB-Programmer when a specific HEX file is loaded

#### Description:

When the HEX file which meets following condition is read, QB-Programmer aborts.

[Condition]

The HEX file by which the value which has added 32 bytes to the file size of the HEX file will be 4096 bytes of multiple

#### Workaround:

There is no workaround.

#### Action:

This issue will be corrected in the next revision.