

Product Advisory Notice (PA)

Subject: Firmware update for the Intersil ISL69144* and ISL69147* Products

Publication Date: 2/22/2017

Effective Date: 2/22/2017

Revision Description:

Initial Release

Description of Change:

This notice is to inform you that Intersil has updated the firmware for the listed ISL69144* and ISL69147* Products

Reason for Change:

This notice is to inform you of a change in internal firmware for the ISL69144* and ISL69147* to correct the behavior when the device is configured as a single output, as opposed to using dual outputs. In this situation, if the AMD processor sends a command to the unused rail, then the device will not issue a VOTFC (Voltage On The Fly Completion). The firmware change is internal and does not affect the users configuration and settings. It will be a transparent upgrade improving single rail operation for VOTFC and the power management setting on the unused rail.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

Affected Products List:

ISL69144IRAZ	ISL69147IRAZ
ISL69144IRAZ-T	ISL69147IRAZ-T
ISL69144IRAZ-T7A	ISL69147IRAZ-T7A

Product Identification:

Product affected by this change is identifiable via Intersil's internal traceability system. There will be no change in external marking of the packaged parts

Qualification status: Not Applicable

Sample availability: 2/22/2017

Device material declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)			
Americas: PCN-US@INTERSIL.COM	Europe: PCN-EU@INTERSIL.COM	Japan: PCN-JP@INTERSIL.COM	Asia Pac: PCN-APAC@INTERSIL.COM