

Product Advisory (PA)

Subject: Change in Device Top Mark for RYZ012A1 and RYZ012B1

Publication Date: 5/17/2022

Effective Date: 5/17/2022

Revision Description:

Initial Revision

Description of Change:

This notice is to advise our customers that Renesas has updated the device top mark for the affected product list to match the datasheet and Renesas marking standards. The new top mark is as depicted in the picture below.



Comparison between the new and the old top marks:

	New Top Mark	Old Top Mark
Top Mark Image		
Marking	FCC and IC marks, and CE label have been added	No FCC and IC marks, no CE label
MIC registration number	New registration number: 202-SMJ030	Old registration number: 202-SMI055

This is top mark update only. There is no other change to the device.

Customers may receive either top mark material until the old top mark material inventory is depleted.

Affected Product List:

RYZ012A100FZ00#BD0	RYZ012B100FZ00#BD0
RYZ012A100FZ00#HD0	RYZ012B100FZ00#HD0

Reason for Change:

Device top mark is updated to match the datasheet and Renesas marking standards.

Impact on Fit, Form, Function, Quality & Reliability:

No change to fit, function quality and reliability of the device.

Product Identification:

Device top mark. All date codes 2208 and after will have the new top mark

Qualification Status: Not Applicable

Sample Availability Date: Not Applicable

Device Material Declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Renesas within 30 days of the publication date.

For additional information regarding this notice, please contact idt-pcn@lm.renesas.com
--