

Product Advisory (PA)

Subject: Remove Package Bottom Mark on the selective Renesas LQFP, PQFP and TQFP products. Publication Date: 11/3/2021

Effective Date: 11/3/2021

Revision Description:

Initial Release

Description of Change:

This notice is to inform you that Renesas Electronics America Inc will remove Country of Origin (COO) and Product Lot Details (Site Code, Date Code, Trace Code) from the bottom of package on the selective Renesas products. Product lot details remains on top of the package and COO is shown on the label. For details of change, please refer to Appendix B.

Reason for Change:

Bottom marking is same as top marking. This is to standardize to existing package marking, to which the product lot is marked on top of the package.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

During the transition, shipments to customers may contain products with or without package bottom mark until the old inventory has been depleted.

Product Identification:

Product affected by this change is identifiable via Renesas's internal traceability system.

Qualification status: Completed, see attached Sample availability: 12/1/2021 Device material declaration: Available upon request

Note:

- 1. Acknowledgement must be received by Renesas within 30 days or Renesas will consider the change as approved.
- 2. If timely acknowledgement is provided by Customer, then Customer shall have 90 days from the date of receipt of this PCN to make any objections to this PCN. If Customer fails to make objections to this PCN within 90 days of the receipt of the PCN then Renesas will consider the PCN changes as approved.
- 3. If customer cannot accept the PCN then customer must provide Renesas with a last time buy demand and purchase order.

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Renesas within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)



Americas: PCN-US@INTERSIL.COM	Europe: PCN-EU@INTERSIL.COM	Japan: PCN-JP@INTERSIL.COM	Asia Pac: PCN-APAC@INTERSIL.COM
-------------------------------	-----------------------------	----------------------------	---------------------------------

Appendix A - Affected Products List (see attached)

Affected Product List

TW2815-TA1-GR TW2865-LA3-GR TW6816A-LA1-CRR5473 TW8823-LC2-CE TW8823AT-LC2-GE TW8823AT-LC2-GE TW8823-LC2-CE TW6816-LA1-GR TW8804-LC3-GRSHT TW8816ATLB3GRSHR5303 TW8811-LD2-GR TW8811-LD2-GR TW8816-LB3-GR TW2824Q-RB TW2834-PA3-GE TW2836-PA1-GE TW2824M-RB TW2837-PB1-GE TW8811-LC2-GR TW8816-LB3-GR TW8816-LB3-GRT TW8816-LB3-GRST TW8816-LA3-GRS TW8816-LA3-GRST TW8816-LA3-GRS TW2835-PA1-GE TW2824M-RB TW2816-TA1-GR TW8817-TA3-GRS TW8817-TA3-GRST TW8811-LD2-GR TW8816-LB3-GRS TW8804-LC3-GRSH TW8816AT-LB3-GRSH TW8816-LB3-GRR5542 TW8816AT-LB3-GRSHT



Appendix A – Details of the change.

