

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

RENESESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	Development Environment		Document No.	TN-CSX-060A/EA	Rev.	1.0
Title	Update of the Integrated Development Environment (HEW3) Ver.3.0.02		Information Category	Specification Change		
Applicable Product	All products that include HEW3	Lot No.	Reference Document	High-performance Embedded Workshop 3 User's Manual Revision 1.0		
		HEW 3.0 (release 21) and 3.01 (release 1)				

We have updated the HEW3 (High-performance Embedded Workshop 3) to be V3.0.02. For details on this, see HS6400EWIW3S-031113E attached to this technical update.

Download the update tool from the following URL:

<http://www.renesas.com/eng/products/mpumcu/tool/index.html>

Attached document: HS6400EWIW3S-031113E

HEW3 (High-performance Embedded Workshop 3) V3.0.02 Update

HEW3 (High-performance Embedded Workshop 3) V3.0.02 Update

We have updated the HEW3 (High-performance Embedded Workshop 3) to be V3.0.02. Details on this update (added function, problems fixed, and notes) are listed below.

1. Function Added

1.1 Navigation Function (Ver. 3.0.02)

Category "C++ Classes" of the navigation function is unchecked at default.

2. Problems Fixed

2.1 HEW Network Database Message Box on Windows® Me (Ver. 3.01)

Display of the network database error message box on Windows® Me is prevented.

2.2 Abnormal Termination (Ver. 3.0.02)

We have fixed the problem that the HEW did not exit normally.

3. Notes

3.1 Added menu (Ver. 3.0.02)

Updating the emulator product by this update tool adds the following menus:

- "Map" menu of the "Memory" menu

3.2 Map window (Ver. 3.0.02)

The map window is not supported in the emulator.