Transient Load Circuit for Buck 1



Set signal generator minimum amplitude at J60 = 1V+, current measurement at J52 is 10mV/1A

Transient Load Circuit for Buck 2



Set signal generator minimum amplitude at J61 = 1V+, current measurement at J55 is 10mV/1A