To our customers,

Old Company Name in Catalogs and Other Documents

   On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

RENESAS

RENESAS TECHNICAL UPD

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-CSX-062A/EA	Rev.	1.0
Title	Update of the Integrated Development Environment (HEW3) Ver.3.0.05		Information Category	Specification Change		
Applicable Product	All products that include HEW3	Lot No.	Reference Document	High-performance Embedded Workshop 3 User's Manual Revision 1.0		
		HEW 3.0.x				

HEW3 (High-performance Embedded Workshop 3) is updated to V3.0.05.

Download the update tool from the following URL:

http://www.renesas.com/eng/products/mpumcu/tool/index.html

Details on this update are listed below.

1. Problems Fixed

1.1 Reload of Files

The problem of not reloading the file when a file currently open in the editor window is edited, saved, and then updated by the external editor, has been corrected. (This problem only occurs with Ver. 3.0.02)

1.2 Problem with the Search Function of the Memory Menu

The problem of an empty [Memory] window with no description being displayed when carrying out a memory search selected from [Memory->Search...] in the menu, has been corrected.

1.3 Symbol Load Command

The problem with the Symbol Load command not operating has been corrected.

RENESAS