[Notes]

CS+ Integrated Development Environment

Outline

When using the CS+ IDE, take note of the problem described in this note regarding the following point.

    1.   Using RH850 compiler (CC-RH) V1.02.00 with CS+ V4.00.00 or V4.00.01.

1. Using RH850 Compiler (CC-RH) V1.02.00 with CS+ V4.00.00 or V4.00.01

1.1 Applicable Product

CS+ Integrated Development Environment V4.00.00 to V4.00.01

1.2 Applicable MCUs

RH850 family

1.3 Details

The following phenomena arise when CS+ V4.00.00 or V4.00.01, and CC-RH V1.02.00 are installed.

(1) In cases where CC-RH V1.02.00 is installed

    Opening projects is not possible.

(2) In cases V1.02.00 and other versions of CC-RH are installed

    V1.02.00 is not displayed as an option in [Using compiler package version] of the [Version Select] category on the [Common Options] tabbed page. The message M0291004 is output when a project is read. The project can be opened with the versions other than CC-RH V1.02.00 in this case.

1.4 Workaround

Uninstall CS+, and install CS+ V3.00.00 or a later version, but earlier than V4.00.00, before using CS+.

1.5 Schedule for Fixing the Problem

This problem will be fixed in the next version of CS+.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Aug. 01, 2016	-	First edition issued

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan

Renesas Electronics Corporation

■Inquiry

http://www.renesas.com/contact/

All trademarks and registered trademarks are the property of their respective owners.