[Upgrade to Revision]
Programming GUI for PG-FP6 Flash Memory Programmer
FP6 Terminal V1.16.00

Outline

FP6 Terminal, a programming GUI for PG-FP6 Flash Memory Programmer, has been updated from V1.15.00 to V1.16.00. For an overview of PG-FP6, refer to the link below.

https://www.renesas.com/pg-fp6

Connect the updated FP6 Terminal to PG-FP6 to update the firmware of PG-FP6.

1. Description

The main changes are as follows. Refer to the release note for details.

(The note is applicable as of April 21.)

https://www.renesas.com/software-tool/pg-fp6#document

1.1 Addition of Supported Devices

(1) RH850 Family

Group	Part number
RH850/U2C4	R7F702606, R7F702606A, R7F702613, R7F702613A, R7F702614, R7F702614A, R7F702616A
RH850/U2C8-EVA	R7F702Z32, R7F702Z32A

1.2 Issue Fixed

The following issue has been fixed.

- RENESAS TOOL NEWS: R20TS1117EJ0100

   1. Address ranges of the V850ES/Jx3

Refer to the tool news below for the details of the problem.

https://www.renesas.com/search?keywords=R20TS1117

1.3

2. Updating the Product

FP6 Terminal can be updated free of charge. Download the installer from the link below.

(The installer is available as of April 21.)

https://www.renesas.com/software-tool/pg-fp6#download

Revision History

Rev.	Date	Description	
		Page	**Summary**
1.00	Apr.20.25	-	First edition issued

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,

Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

TS Colophon 4.3