



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: U-12-03R1

Last Buy Deadline for Submission of Order: 9-Feb-2013

Issue Date: 5-Mar-2012

Last Eligible Ship Date: 9-May-2013

Contact: Russell Willner
Title: Marketing Manager - Micro Clock Products
Phone #: 408-284-6564
Fax #: 408-284-2774
E-mail: Russell.Willner@idt.com

PRODUCT(S) AFFECTED: **ATTACHMENT** ☒ Yes ☐ No

(List Replacement Part #(s), if any)

Revision 1: This revised notification is to remove MK2308G-1HLF, MK2308G-1HLFT, MK2304S-2LF, MK2304S-2LFT, MK2302S-01LF and MK2302S-01LFT from the product discontinuance notice.

Please refer to Attachment I for the updated discontinued part numbers.

REASON FOR DISCONTINUANCE:

- ☐ Replace slower speed with faster speed offerings ☐ Other: _____
- ☐ Obsolete Fab Technology / Process _____
- ☐ Obsolete Assembly Technology / Process _____
- ☐ Obsolete Package / Material _____
- ☒ Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax#: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: U-12-03R1

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
1524AMLF	None	570M	570MLF
1524AMLFT	None	570MI	570MILF
2308-2HDCGI	None	570MIT	570MILFT
2308-2HDCGI8	None	570MT	570MLFT
3732AG-32LF	None	650G-36LF	None
3732AG-32LFT	None	650G-36LFT	None
3732DG-32LF	None	650G-40ALF	None
3732DG-32LFT	None	650G-40ALFT	None
3732G-33LF	None	650G-40LF	None
3732G-33LFT	None	650G-40LFT	None
409MLF	None	650R-14LF	None
409MLFT	None	650R-14LFT	None
422M-01LF	None	664G-04LF	None
422M-01LFT	None	664G-04LFT	None
422M-02LF	None	664G-05LF	None
422M-02LFT	None	664G-05LFT	None
441M-36LF	None	667M-01LF	None
441M-36LFT	None	667M-01LFT	None
448R-13LF	None	670AM-01LF	None
448R-13LFT	None	670AM-01LFT	None
452M-19LF	None	6P40118PGG	None
452M-19LFT	None	6P40118PGG8	None
475G-14LF	None	6P40189NDGI	None
475G-14LFT	None	6P40189NDGI8	None
475G-17LF	None	6P40189NLGI	None
475G-17LFT	None	6P40189NLGI8	None
475G-21LF	None	6V40111ANLGI	None
475G-21LFT	None	6V40111ANLGI8	None
476EG-08LF	None	6V49061PAG	None
476EG-08LFT	None	6V49061PAG8	None
480G-49LF	None	MK1714-02RLF	None
480G-49LFT	None	MK1714-02RLFT	None
527R-02ILF	None	MK1716-01RLF	None
527R-02ILFT	None	MK1716-01RLFT	None
527R-03LF	None	MK1725GLF	None
527R-03LFT	None	MK1725GLFT	None
556G-03ILF	None	MK1728-01SLF	None
556G-03ILFT	None	MK1728-01SLFT	None
570A	570ALF	MK2746-01GLF	None
570AI	570AILF	MK2746-01GLFT	None
570AIT	570AILFT	MK3732-26GLF	None
570AT	570ALFT	MK3732-26GLFTR	None
570B	570BLF	MK3732-27GLF	None
570BI	570BILF	MK3732-27GLFTR	None
570BIT	570BILFT	MK74CG117AF	None
570BT	570BLFT	MK74CG117AFT	None