

List of EOL Products Supported for Repair ^(*1)

Product name	Repair period ^(*2)
M32100T5-SDI-E	Until the end of November 2023
QB-78F1026-ZZZ	Until the end of November 2023
QB-78K0DX2-ZZZ	Until the end of November 2023
QB-78K0FX2L-ZZZ	Until the end of November 2023
QB-78K0FX2-ZZZ	Until the end of November 2023
QB-78K0IX2-ZZZ	Until the end of November 2023
QB-78K0KX2C-ZZZ	Until the end of November 2023
QB-78K0KX2L-ZZZ	Until the end of November 2023
QB-78K0KX2-ZZZ	Until the end of November 2023
QB-78K0LX3-ZZZ	Until the end of November 2023
QB-78K0RFX3-ZZZ	Until the end of November 2023
QB-78K0RIX3-ZZZ	Until the end of November 2023
QB-78K0RKX3-ZZZ	Until the end of November 2023
QB-78K0RLX3-ZZZ	Until the end of November 2023
QB-78K0SKX1-ZZZ	Until the end of November 2023
QB-V850E2-EE	Until the end of November 2023
QB-V850E2FX4H-PD	Until the end of November 2024
QB-V850E2SX4H-PD	Until the end of November 2024
M3062PT3-CPE	Until the end of May 2025
M30850T3-CPE	Until the end of May 2025
M30870T2-CPE	Until the end of May 2025
ROE530640MCU00	Until the end of May 2025

(*1) This table lists the product names of the MCU development tools supported for repair after discontinuation.

(*2) For repair reception period, refer to "How to Request Inspection and Repair for Tools" from the URL below.

<https://www.renesas.com/products/software-tools/repair-information.html>

The set items are not listed in this list, but if the products included in the set item are the products to be repaired and are within the repair period, the repair can be accepted.