

PRODUCT DISCONTINUANCE # CQ-14-05

ISSUE DATE: July 31, 2014

LAST TIME BUY DATE: July 31, 2015

LAST TIME SHIP DATE: October 31, 2015

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of the attached list of IDT products.

Some of these products may have an alternate IDT part number as a drop in replacement or a suggested functional replacement.

Customer should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuation Notice. They may also contact their local IDT Sales Office listed on the IDT website at www.idt.com or the Marketing contact listed below. The affected parts lists show the applicable product marketing group.

<u>Product Group</u>	<u>Product Group Contact Information</u>
MMT	Victory Abarca (Victor.Abarca@idt.com) Phone# (408) 284-6578
SPO	Carl May (Carl.May@idt.com) Phone (408) 284-2718
NWC	clocks@idt.com
MIP	Paul Barton (Paul.Barton@idt.com) Phone (408) 284 8306

Last time buy orders may be submitted any time prior to the last time buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance	Replacement Part Availability	Product Group
181M-01LF	-	-	Market Decline	N/A	MMT
181M-01LFT	-	-	Market Decline	N/A	MMT
181M-02LF	-	-	Market Decline	N/A	MMT
181M-02LFT	-	-	Market Decline	N/A	MMT
181M-51LF	-	-	Market Decline	N/A	MMT
181M-51LFT	-	-	Market Decline	N/A	MMT
2308B-4DCG	-	-	Market Decline	N/A	MMT
2308B-4DCG8	-	-	Market Decline	N/A	MMT
5V19EE603NDGI	-	-	Market Decline	N/A	MMT
5V19EE603NDGI8	-	-	Market Decline	N/A	MMT
5V50015DCG	-	-	Market Decline	N/A	MMT
5V50015DCG8	-	-	Market Decline	N/A	MMT
5V50015PGG	-	-	Market Decline	N/A	MMT
5V50015PGG8	-	-	Market Decline	N/A	MMT
72801L10TF	-	72801L10PF	Market Decline	Now	SPO
72801L10TF8	-	72801L10PF8	Market Decline	Now	SPO
72801L15TF	-	72801L15PF	Market Decline	Now	SPO
72801L15TF8	-	72801L15PF8	Market Decline	Now	SPO
72801L15TFI	-	72801L15PFI	Market Decline	Now	SPO
72801L15TFI8	-	72801L15PFI8	Market Decline	Now	SPO
72801L25TF	-	72801L25PF	Market Decline	Now	SPO
72801L25TF8	-	72801L25PF8	Market Decline	Now	SPO
72801L25TFI	-	72801L25PFI	Market Decline	Now	SPO
72801L25TFI8	-	72801L25PFI8	Market Decline	Now	SPO
72811L10TF	-	72811L10PF	Market Decline	Now	SPO
72811L10TF8	-	72811L10PF8	Market Decline	Now	SPO
72811L10TFG	-	72811L10PFG	Market Decline	Now	SPO
72811L10TFG8	-	72811L10PFG8	Market Decline	Now	SPO
72811L15TF	-	72811L15PF	Market Decline	Now	SPO
72811L15TF8	-	72811L15PF8	Market Decline	Now	SPO
72811L15TFI	-	72811L15PFI	Market Decline	Now	SPO
72811L15TFI8	-	72811L15PFI8	Market Decline	Now	SPO
72811L25TF	-	72811L25PF	Market Decline	Now	SPO
72811L25TF8	-	72811L25PF8	Market Decline	Now	SPO
72811L25TFI	-	72811L25PFI	Market Decline	Now	SPO
72811L25TFI8	-	72811L25PFI8	Market Decline	Now	SPO
72821L10TF	-	72821L10PF	Market Decline	Now	SPO
72821L10TF8	-	72821L10PF8	Market Decline	Now	SPO
72821L15TF	-	72821L15PF	Market Decline	Now	SPO
72821L15TF8	-	72821L15PF8	Market Decline	Now	SPO
72821L15TFI	-	72821L15PFI	Market Decline	Now	SPO
72821L15TFI8	-	72821L15PFI8	Market Decline	Now	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance	Replacement Part Availability	Product Group
72821L25TF	-	72821L25PF	Market Decline	Now	SPO
72821L25TF8	-	72821L25PF8	Market Decline	Now	SPO
72821L25TFI	-	72821L25PFI	Market Decline	Now	SPO
72821L25TFI8	-	72821L25PFI8	Market Decline	Now	SPO
72831L10TF	-	72831L10PF	Market Decline	Now	SPO
72831L10TF8	-	72831L10PF8	Market Decline	Now	SPO
72831L15TF	-	72831L15PF	Market Decline	Now	SPO
72831L15TF8	-	72831L15PF8	Market Decline	Now	SPO
72831L15TFI	-	72831L15PFI	Market Decline	Now	SPO
72831L15TFI8	-	72831L15PFI8	Market Decline	Now	SPO
72831L25TF	-	72831L25PF	Market Decline	Now	SPO
72831L25TF8	-	72831L25PF8	Market Decline	Now	SPO
72831L25TFI	-	72831L25PFI	Market Decline	Now	SPO
72831L25TFI8	-	72831L25PFI8	Market Decline	Now	SPO
72841L10TF	-	72841L10PF	Market Decline	Now	SPO
72841L10TF8	-	72841L10PF8	Market Decline	Now	SPO
72841L10TFG	-	72841L10PFG	Market Decline	Now	SPO
72841L10TFG8	-	72841L10PFG8	Market Decline	Now	SPO
72841L15TF	-	72841L15PF	Market Decline	Now	SPO
72841L15TF8	-	72841L15PF8	Market Decline	Now	SPO
72841L15TFI	-	72841L15PFI	Market Decline	Now	SPO
72841L15TFI8	-	72841L15PFI8	Market Decline	Now	SPO
72841L25TF	-	72841L25PF	Market Decline	Now	SPO
72841L25TF8	-	72841L25PF8	Market Decline	Now	SPO
72841L25TFI	-	72841L25PFI	Market Decline	Now	SPO
72841L25TFI8	-	72841L25PFI8	Market Decline	Now	SPO
72851L10TF	-	72851L10PF	Market Decline	Now	SPO
72851L10TF8	-	72851L10PF8	Market Decline	Now	SPO
72851L15TF	-	72851L15PF	Market Decline	Now	SPO
72851L15TF8	-	72851L15PF8	Market Decline	Now	SPO
72851L15TFI	-	72851L15PFI	Market Decline	Now	SPO
72851L15TFI8	-	72851L15PFI8	Market Decline	Now	SPO
72851L25TF	-	72851L25PF	Market Decline	Now	SPO
72851L25TF8	-	72851L25PF8	Market Decline	Now	SPO
72851L25TFI	-	72851L25PFI	Market Decline	Now	SPO
72851L25TFI8	-	72851L25PFI8	Market Decline	Now	SPO
72V801L10TF	-	72V801L10PF	Market Decline	Now	SPO
72V801L10TF8	-	72V801L10PF8	Market Decline	Now	SPO
72V801L15TF	-	72V801L15PF	Market Decline	Now	SPO
72V801L15TF8	-	72V801L15PF8	Market Decline	Now	SPO
72V801L15TFI	-	72V801L15PFI	Market Decline	Now	SPO
72V801L15TFI8	-	72V801L15PFI8	Market Decline	Now	SPO
72V801L20TF	-	72V801L20PF	Market Decline	Now	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance	Replacement Part Availability	Product Group
72V801L20TF8	-	72V801L20PF8	Market Decline	Now	SPO
72V811L10TF	-	72V811L10PF	Market Decline	Now	SPO
72V811L10TF8	-	72V811L10PF8	Market Decline	Now	SPO
72V811L15TF	-	72V811L15PF	Market Decline	Now	SPO
72V811L15TF8	-	72V811L15PF8	Market Decline	Now	SPO
72V811L15TFI	-	72V811L15PFI	Market Decline	Now	SPO
72V811L15TFI8	-	72V811L15PFI8	Market Decline	Now	SPO
72V811L20TF	-	72V811L20PF	Market Decline	Now	SPO
72V811L20TF8	-	72V811L20PF8	Market Decline	Now	SPO
72V821L10TF	-	72V821L10PF	Market Decline	Now	SPO
72V821L10TF8	-	72V821L10PF8	Market Decline	Now	SPO
72V821L15TF	-	72V821L15PF	Market Decline	Now	SPO
72V821L15TF8	-	72V821L15PF8	Market Decline	Now	SPO
72V821L15TFI	-	72V821L15PFI	Market Decline	Now	SPO
72V821L15TFI8	-	72V821L15PFI8	Market Decline	Now	SPO
72V821L20TF	-	72V821L20PF	Market Decline	Now	SPO
72V821L20TF8	-	72V821L20PF8	Market Decline	Now	SPO
72V831L10TF	-	72V831L10PF	Market Decline	Now	SPO
72V831L10TF8	-	72V831L10PF8	Market Decline	Now	SPO
72V831L15TF	-	72V831L15PF	Market Decline	Now	SPO
72V831L15TF8	-	72V831L15PF8	Market Decline	Now	SPO
72V831L15TFI	-	72V831L15PFI	Market Decline	Now	SPO
72V831L15TFI8	-	72V831L15PFI8	Market Decline	Now	SPO
72V831L20TF	-	72V831L20PF	Market Decline	Now	SPO
72V831L20TF8	-	72V831L20PF8	Market Decline	Now	SPO
72V841L10TF	-	72V841L10PF	Market Decline	Now	SPO
72V841L10TF8	-	72V841L10PF8	Market Decline	Now	SPO
72V841L15TF	-	72V841L15PF	Market Decline	Now	SPO
72V841L15TF8	-	72V841L15PF8	Market Decline	Now	SPO
72V841L15TFI	-	72V841L15PFI	Market Decline	Now	SPO
72V841L15TFI8	-	72V841L15PFI8	Market Decline	Now	SPO
72V841L20TF	-	72V841L20PF	Market Decline	Now	SPO
72V841L20TF8	-	72V841L20PF8	Market Decline	Now	SPO
72V851L10TF	-	72V851L10PF	Market Decline	Now	SPO
72V851L10TF8	-	72V851L10PF8	Market Decline	Now	SPO
72V851L15TF	-	72V851L15PF	Market Decline	Now	SPO
72V851L15TF8	-	72V851L15PF8	Market Decline	Now	SPO
72V851L15TFI	-	72V851L15PFI	Market Decline	Now	SPO
72V851L15TFI8	-	72V851L15PFI8	Market Decline	Now	SPO
72V851L20TF	-	72V851L20PF	Market Decline	Now	SPO
72V851L20TF8	-	72V851L20PF8	Market Decline	Now	SPO
74ALVCH162374PAG	-	-	Market Decline	N/A	SPO
74ALVCH162374PAG8	-	-	Market Decline	N/A	SPO



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance	Replacement Part Availability	Product Group
74ALVCH16260PAG	-	-	Market Decline	N/A	SPO
74ALVCH16260PAG8	-	-	Market Decline	N/A	SPO
74ALVCH32374BF	-	-	Market Decline	N/A	SPO
74ALVCH32374BF8	-	-	Market Decline	N/A	SPO
74ALVCH32374BFG	-	-	Market Decline	N/A	SPO
74ALVCH32374BFG8	-	-	Market Decline	N/A	SPO
74LVC162244APFG	-	74LVC162244APAG	Market Decline	Now	SPO
74LVC162244APFG8	-	74LVC162244APAG8	Market Decline	Now	SPO
74LVC162245APFG	-	74LVC162245APAG	Market Decline	Now	SPO
74LVC162245APFG8	-	74LVC162245APAG8	Market Decline	Now	SPO
74LVC16374APFG	-	74LVC16374APAG	Market Decline	Now	SPO
74LVC16374APFG8	-	74LVC16374APAG8	Market Decline	Now	SPO
74LVC16374APVG	-	74LVC16374APAG	Market Decline	Now	SPO
74LVC16374APVG8	-	74LVC16374APAG8	Market Decline	Now	SPO
74LVC16601APVG	-	-	Market Decline	N/A	SPO
74LVC16601APVG8	-	-	Market Decline	N/A	SPO
74LVCH162244APFG	-	74LVCH162244APAG	Market Decline	Now	SPO
74LVCH162244APFG8	-	74LVCH162244APAG8	Market Decline	Now	SPO
74LVCH162373APVG	-	74LVCH162373APAG	Market Decline	Now	SPO
74LVCH162373APVG8	-	74LVCH162373APAG8	Market Decline	Now	SPO
74LVCH16373APAG	-	-	Market Decline	N/A	SPO
74LVCH16373APAG8	-	-	Market Decline	N/A	SPO
74LVCH16646APAG	-	-	Market Decline	N/A	SPO
74LVCH16646APAG8	-	-	Market Decline	N/A	SPO
74LVCR162245APVG	-	74LVCR162245APAG	Market Decline	Now	SPO
74LVCR162245APVG8	-	74LVCR162245APAG8	Market Decline	Now	SPO
74SSTVF16859PAG	SSTVA16859CGLF	-	Market Decline	Now	MIP
74SSTVF16859PAG8	SSTVA16859CGLFT	-	Market Decline	Now	MIP
810252AKI-03LF	-	810252DKI-02LF, 8T49N282B-dddNLGI	Market Decline	Now	NWC
810252AKI-03LFT	-	810252DKI-02LFT, 8T49N282B-dddNLGI8	Market Decline	Now	NWC
810252AYI-03LF	-	810252DKI-02LF, 8T49N282B-dddNLGI	Market Decline	Now	NWC
810252AYI-03LFT	-	810252DKI-02LFT, 8T49N282B-dddNLGI8	Market Decline	Now	NWC
810252BKI-02LF	810252DKI-02LF	-	Market Decline	Now	NWC
810252BKI-02LFT	810252DKI-02LFT	-	Market Decline	Now	NWC
810252BKI-03LF	-	810252DKI-02LF, 8T49N282B-dddNLGI	Market Decline	Now	NWC
810252BKI-03LFT	-	810252DKI-02LFT, 8T49N282B-dddNLGI8	Market Decline	Now	NWC
810252BYI-03LF	-	810252DKI-02LF, 8T49N282B-dddNLGI	Market Decline	Now	NWC
810252BYI-03LFT	-	810252DKI-02LFT, 8T49N282B-dddNLGI8	Market Decline	Now	NWC
813252CKI-02LF	-	813N252CKI-02LF	Market Decline	Now	NWC
813252CKI-02LFT	-	813N252CKI-02LFT	Market Decline	Now	NWC
813323BGLF	-	8T49N282B-dddNLGI	Market Decline	Now	NWC
813323BGLFT	-	8T49N282B-dddNLGI8	Market Decline	Now	NWC



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Direct Replacement	Functional Replacement	Reason for Discontinuance	Replacement Part Availability	Product Group
840304BGILF	-	8T49N282B-dddNLGI	Market Decline	Now	NWC
840304BGILFT	-	8T49N282B-dddNLGI8	Market Decline	Now	NWC
8422002AGILF	-	8422002AGI-07LF	Market Decline	Now	NWC
8422002AGILFT	-	8422002AGI-07LFT	Market Decline	Now	NWC
843034AY-01LF	-	843034EY-06LF, 843034CYLF	Market Decline	Now	NWC
843034AY-01LFT	-	843034EY-06LFT, 843034CYLFT	Market Decline	Now	NWC
843051AGILF	843051AGLF	-	Market Decline	Now	NWC
843051AGILFT	843051AGLFT	-	Market Decline	Now	NWC
8432CY-111LF	-	8432DY-101LF	Market Decline	Now	NWC
8432CY-111LFT	-	8432DY-101LFT	Market Decline	Now	NWC
843312AKLF	-	-	Market Decline	N/A	NWC
843312AKLFT	-	-	Market Decline	N/A	NWC
843S1066CGLF	843S1066DGLF	-	Market Decline	Now	NWC
843S1066CGLFT	843S1066DGLFT	-	Market Decline	Now	NWC
843S2807DYL F	-	8T49N282B-dddNLGI	Market Decline	Now	NWC
843S2807DYLFT	-	8T49N282B-dddNLGI8	Market Decline	Now	NWC
844004AGI-04LF	-	-	Market Decline	N/A	NWC
844004AGI-04LFT	-	-	Market Decline	N/A	NWC
8440259AK-05LF	8440259DK-05LF	-	Market Decline	Now	NWC
8440259AK-05LFT	8440259DK-05LFT	-	Market Decline	Now	NWC
8440259AK-45LF	8440259DK-45LF	-	Market Decline	Now	NWC
8440259AK-45LFT	8440259DK-45LFT	-	Market Decline	Now	NWC
85211AMILF	-	85211BMI-03LN	Market Decline	Now	NWC
85211AMILFT	-	85211BMI-03LNT	Market Decline	Now	NWC
8532AY-01LF	-	8530DYLF	Market Decline	Now	NWC
8532AY-01LFT	-	8530DYLFT	Market Decline	Now	NWC
8535AG-11LF	-	8533AG-11LF	Market Decline	Now	NWC
8535AG-11LFT	-	8533AG-11LFT	Market Decline	Now	NWC
8535AGI-11LF	-	8533AG-11LF	Market Decline	Now	NWC
8535AGI-11LFT	-	8533AG-11LFT	Market Decline	Now	NWC
8538BGI-26LF	-	-	Market Decline	N/A	NWC
8538BGI-26LFT	-	-	Market Decline	N/A	NWC
873990AYLF	-	-	Market Decline	N/A	NWC
873990AYLFT	-	-	Market Decline	N/A	NWC
95V842AFILF	-	-	Market Decline	N/A	MIP
95V842AFILF8	-	-	Market Decline	N/A	MIP
95V842AFLF	-	-	Market Decline	N/A	MIP
95V842AFLF8	-	-	Market Decline	N/A	MIP