

## Product Lifecycle Notice

**Subject:** Product Discontinuance / Obsolescence Notification

**Publication Date:** 10/31/2016

**Revision Description:**

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the list on the following page and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC16094 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL8202W	10/31/2016	4/30/2017	10/30/2017	None
HIP4082IBZTS2366A	10/31/2016	4/30/2017	10/30/2017	HIP4082IBZT
ICM7244AIM44Z	10/31/2016	4/30/2017	10/30/2017	ICM7244BIM44Z
ICM7244AIM44ZT	10/31/2016	4/30/2017	10/30/2017	ICM7244BIM44ZT
ISL12025DBEV1Z	10/31/2016	4/30/2017	10/30/2017	None
ISL12025IBZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12025IBZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB27AZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB27AZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB27Z	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB27Z-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB30AZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IB30AZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IBA	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IBAZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IBZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IBZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV27AZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV27AZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV27Z	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV27Z-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV30AZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12027IV30AZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IB27Z	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IB27Z-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IBZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IBZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IV27Z	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IV27Z-T	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IVZ	10/31/2016	4/30/2017	10/30/2017	None
ISL12028IVZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL53570IQZR5267	10/31/2016	4/30/2017	10/30/2017	None
ISL54052IHZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL54052IRUZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL54216IRUZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL54216IRUZ-T7A	10/31/2016	4/30/2017	10/30/2017	None
ISL54217IRUZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL54233IRUZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL54233IRUZ-T7A	10/31/2016	4/30/2017	10/30/2017	None
ISL54233IRUZ-TS2722	10/31/2016	4/30/2017	10/30/2017	None
ISL59448EVAL1Z	10/31/2016	4/30/2017	10/30/2017	None
ISL59602IRZ-T7A	10/31/2016	4/30/2017	10/30/2017	None
ISL76123AHZ-T	10/31/2016	4/30/2017	10/30/2017	None
ISL76123AHZ-T7A	10/31/2016	4/30/2017	10/30/2017	None
TW6874-BB1-CR	10/31/2016	4/30/2017	10/30/2017	None
TW6874-BB1-CR-EVALZ	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8IZ	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8IZ-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8IZ-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8IZT1	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8Z	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8Z-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8Z-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TM8ZT1	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8IZ	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8IZ-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8IZ-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8Z	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8Z-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317TS8Z-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8IZ	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8IZ-2.7	10/31/2016	4/30/2017	10/30/2017	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC16094 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9317TV8IZ-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8IZT1	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8Z	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8Z-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8Z-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317TV8ZT1	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8IZ	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8IZ-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8IZ-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8IZT1	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8Z	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8Z-2.7	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8Z-2.7T1	10/31/2016	4/30/2017	10/30/2017	None
X9317UM8ZT1	10/31/2016	4/30/2017	10/30/2017	None