



Transient Load Circuit for Buck 3




Set signal generator minimum amplitude at J62 = 1V+, current measurement at J59 is 10mV/1A

Transient Load Circuit for Buck 4



Set signal generator minimum amplitude at J66 = 1V+, current measurement at J67 is 10mV/1A



Ouput sense resistors for each rail.

