
PRODUCT ADVISORY

Data Sheet Specification Change for Intersil Product ISL78205AVEZ*

**Refer to:
PA12062**

Date: August 15, 2012

August 15, 2012

To: Our Valued Intersil Customer

Subject: **Data Sheet Specification Change for Intersil Product ISL78205AVEZ***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL78205AVEZ* products. The *Electrical Specifications* (sheet 7) table updates include the addition of parameters, conditions, and performance values associated with the Synchronization function of the device. The updates to the *Functional Description* (sheets 12 – 14) sections for Input Voltage, Oscillator and Synchronization, Fault Protection, and Component Selection provide additional clarity and details as to the features and operation of the device. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn7926.pdf>.

Products affected:

ISL78205AVEZ ISL78205AVEZ-T ISL78205AVEZ-TR5303 ISL78205AVEZ-TR5506

There will be no change in external marking of the packaged parts. There have been no changes made to the silicon or device itself.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster
Intersil Corporation

PA12062

CC: J. Touvell M. Holdaway R. Shia