

RENESAS TOOL NEWS on June 16, 2004: RSO-M3062PT-EPB-040616D

Emulation Probe M3062PT-EPB and Pod M3062PT3-RPD-E Upgraded Free of Charge

We will upgrade the M3062PT-EPB emulation probe (used with the PC7501 emulator) and the M3062PT3-RPD-E emulation pod (used with the PC4701 emulator) for the M16C/62P group in the M16C/60 series MCUs free of charge.

1. Products Concerned

1.1 M3062PT-EPB Emulation Probe Used with the PC7501

The products with the following serial numbers as well as the ES products are concerned. The serial number is inscribed on the label affixed to the M3062PT-EPBM board:

| Product Type | Serial No. | Pcs | Remarks |
|------------------|-----------------------|-----|------------------------|
| M3062PT-EPB | With label of ES TOOL | 51 | ES products |
| | 2JS0001--2JS0025 | 25 | Specific products |
| | 2KS0026--2KS0050 | 25 | |
| | 2LS0051--2LS0150 | 100 | |
| | 3AS0151A--3AS0200A | 50 | mass-produced products |
| | 3BS0201A--3BS0250A | 50 | |
| | 3CS0251A--3CS0300A | 50 | |
| | 3HI001--3HI100 | 100 | |
| | 3KI001--3KI050 | 50 | |
| | 3LI001--3LI050 | 50 | |
| | 4CI001--4CI050 | 50 | |
| | 3BS9001--3BS9051 | 51 | |
| | 3CS9052--3CS9201 | 150 | |
| 3GS9202--3GS9251 | 50 | | |

1.2 M3062PT3-RPD-E (or M3062PT3-RPD) Emulation Pod Used with the PC4701

The products on the bottom of which the following serial number is inscribed are concerned:

| Product Type | Serial No. | Pcs | Remarks |
|----------------|--------------------|-----|---------------------------|
| M3062PT3-RPD | 2JM001, 2JM002 | 2 | WS(TS) products |
| | 2KM003--2KM005 | 3 | |
| | 2LM006--2LM026 | 21 | |
| | 3BM027--3BM050 | 24 | |
| | 3CM051--3CM096 | 46 | |
| M3062PT3-RPD-E | 3DS001--3DS030 | 30 | mass-produced products |
| | 3ES031A--3ES039A | 9 | |
| | 3ES040B, 3ES041B | 2 | |
| | 3ES042A--3ES047A | 6 | |
| | 3ES048B, 3ES049B | 2 | |
| | 3ES050A | 1 | |
| | 3GS051B--3GS080B | 30 | |
| | 3HS081B--3HS110B | 30 | |
| | 3JS111B--3JS140B | 30 | |
| | 4AS0141C--4AS0170C | 30 | |
| | 4ES0171C--4ES0190C | 20 | |

2. Description of Upgrade

The following known problem described in Technical Update "M16C Family Precautions when Using Sub Clock" (PDF 61KB) issued on January 5, 2004 (TN-16C-119A/EA) has been fixed.

3. How to Upgrade the Product You want

(1) Application for the Upgrade

Fill in the appended "M3062PT-EPB/M3062PT3-RPD-E Free-of-Charge Upgrade Application Form" and send it by e-mail or FAX to your local Renesas Technology sales office or distributor.

(2) Shipment of the boards on which the upgraded MCU mounted

We will ship the following upgraded boards from July 1:

- M3062PT-EPBM board for the M3062PT-EPB emulation probe
- M3062PT3-PRTM board for the M3062PT3-RPD-E emulation pod

- (3) How to substitute the upgraded board for yours
- Substitute the upgraded board for yours following the manual(*) of substituting each board included with the upgraded board; then check to see that the substituted board operates properly.
*: The manual for M3062PT-EPBM (PDF file, 210 KB)
The manual for M3062PT3-PRTM (PDF file, 214 KB)
 - After checking it, send your previous board to your local Renesas Technology sales office or distributor.

4. **Effective Date of Application**

From July 1, 2004 through December 31, 2004 (to be received by us)

If circumstances prevent you from sending your application form within the above date, please contact your local Renesas Technology sales office or distributor.

5. **Shipment of the Upgraded Boards**

We will ship the upgraded boards after the end of July. It will take 10 working days or more to ship the product you want after receiving your application form (except for the transportation period).

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.