



Revision List
referred to on Certificate No.: 968/FSP 1642.01/23
Renesas Diagnostic Software for RX100 MCU series



Safety related modules / components

Type Designation / Description	SW Revision	Report-No.:	Certification Status
Renesas Diagnostics Software for RX111, RX113, RX130 Groups and IAR EWRX compiler	3.00a	968/FSP 1642.00/18	<i>Valid</i>
Renesas Diagnostics Software for RX111, RX113, RX130 Groups and Renesas CC-RX compiler	3.00b	968/FSP 1642.00/18	<i>Valid</i>

Safety Manual / User documentation

Document No.	Revision	Report-No.:	Certification Status
Renesas Diagnostics Software Safety Manual File: r30uz0104ej0300.pdf	3.00	968/FSP 1642.00/18	<i>Valid</i>
Renesas Diagnostic Software User Guide for IAR version File: r30uz0106ej0300-iar.pdf	3.00a	968/FSP 1642.00/18	<i>Valid</i>
Renesas Diagnostic Software User Guide for CC-RX version File: r30uz0105ej0300-ccrx.pdf	3.00b	968/FSP 1642.00/18	<i>Valid</i>

Revision:

Date	Rev.	Description / Changes	Author
2018-06-05	1.0	Initial creation, based on Report-No.: 968/FSP 1642.00/18	fba/A-FS
2023-11-14	2.0	Report and update assessment for the renewal of the certificate	ms/A-FS