

[Notes]

R20TS0780EJ0100

Rev.1.00

Dec. 16, 2021

RX Family

S12AD Module Using Firmware Integration Technology,

RX Driver Package

Outline

When using the product in the title, note the following point.

1. Note on setting the S12AD1 pin of RX671 with the Smart Configurator

1. Note on Setting the S12AD1 Pin of RX671 with the Smart Configurator

1.1 Applicable Products

- (1) S12AD module using Firmware Integration Technology (S12AD FIT module)

The applicable revisions and documents are as follows.

Table 1.1 S12AD FIT module applicable products

Revision	Document number
Rev.4.90	R01AN1666EJ0490
Rev.4.80	R01AN1666EJ0480

- (2) RX Driver Package

The S12AD FIT modules in (1) are also included in the RX Driver Packages.

The product names and revisions of the packages and the revisions and documents of the S12AD FIT module are as follows.

Table 1.2 Products that include the S12AD FIT module

RX Driver Package product name	RX Driver Package revision	Document number	S12AD FIT module revision
RX Driver Package for RX Family, Ver.1.32	Rev.1.32	R01AN6013EJ0132	Rev.4.90
RX Driver Package for RX Family, Ver.1.31	Rev.1.31	R01AN5975EJ0131	Rev.4.80

1.2 Applicable Devices

RX671 group

1.3 Details and Condition

The S12AD1 pin of RX671 does not appear in the Smart Configurator software component configuration so it cannot be set.

1.4 Schedule for Fixing the Problem

(1) S12AD FIT module

Use Rev.4.91 or later.

(2) RX Driver Package

The problem will be fixed in the future release.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Dec.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/