

RENESAS TOOL NEWS on December 16, 2005: RSO-E200F_1-051216D

The Emulator Software for the E200F emulator R0E0200F0EMU00 Revised to V.1.04 Release 00

We have revised the emulator software for the E200F emulator R0E0200F0EMU00 to V.1.04 Release 00. The emulator supports specific group/series of the SuperH RISC engine MCU family together with the emulator software.

1. Product and Versions Concerned

The emulator software V.1.00 Release 00 through V.1.03 Release 00 for the E200F emulator R0E0200F0EMU00

The emulator and the emulator software support the following MCUs of the SuperH RISC engine Family:

- SH7780 group, SH7780 series (SH-4A-cored)
- SH-Mobile series (SH4AL-DSP-cored)

2. Descriptions of Revision

2.1 The SH7338, SH7348, and SH7343 MCUs have been added to the support line.

2.2 Problem Fixed

The known problem on loading user programs to the emulator has been fixed. For details, see RENESAS TOOL NEWS "A Note on Using the E200F Emulators" (NO. RSO-E200F_2-051216D), issued on Dec. 16, 2005.

3. How to Update Your Product

Free-of-charge online update is available. If you are using the product and versions concerned, follow these steps:

- (1) Download the update program (a ZIP file) from Download

site.

- (2) Decompress the downloaded file to obtain the install program (a setup.exe file) and execute it.

4. **Notice**

If the install program is executed in the system where the High- performance Embedded Workshop V.4.00.02 or earlier resides, it will be upgraded to V.4.00.03.

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.