[Upgrade to revision]

Programming GUI (FP6 Terminal)

for PG-FP6 Flash Memory Programmer V1.03.01

R20TS0418EJ0100 Rev.1.00 Apr. 16, 2019

Outline

We have updated the programming GUI (FP6 Terminal) for the PG-FP6 flash memory programmer from V1.03.00 to V1.03.01. For an overview of the PG-FP6, refer to the URL below. https://www.renesas.com/pg-fp6

1. Description of the Update

1.1 Addition of Supported Devices

Support has been added to the following devices.

(1) RH850 Family

Group	Part number		
RH850/F1KH	R7F701708, R7F701709, R7F701710, R7F701711, R7F701714, R7F701715		
RH850/F1KM	R7F701652, R7F701653		
	R7F701417, R7F701437		

(2) RX family

Group	Part number		
RX66T	R5F566TFA, R5F566TFB, R5F566TFC, R5F566TFE, R5F566TFF, R5F566TFG, R5F566TKA, R5F566TKB, R5F566TKC, R5F566TKE, R5F566TKF, R5F566TKG		

1.2 Issues Fixed

The problem described in the following note has been fixed.

- RENESAS TOOL NEWS, Document No. R20TS0399EJ0100
 - 1. Point for caution regarding enabling of the intelligent cryptographic unit slave E (ICUSE) of the RH850/C1M-A, RH850/F1K, RH850/F1KM-S1, RH850/P1L-C, and RH850/P1M-E groups

For details about this problem, refer to the following URL. https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0399

2. Updating Your Product

FP6 Terminal can be updated online free of charge. Download the installer from the following URL for an installation. (The installer will be available on April 22.) https://www.renesas.com/pg-fp6#downloads



Revision History

		Description		
Rev.	Date	Page	Summary	
1.00	Apr.16.19	-	First edition issued	

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

URLs in Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

© 2019. Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.0