

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification Products

Publication Date: 12/23/2015

Revision Description:

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC15066 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
D2-71683-LR	12/23/2015	6/23/2016	12/23/2016	D2-71583-LR
D2-81433-LR	12/23/2015	6/23/2016	12/23/2016	D2-81435-LR
D2-92613-LR	12/23/2015	6/23/2016	12/23/2016	none
D2-92625-LR	12/23/2015	6/23/2016	12/23/2016	none
D2MC-72083-LR	12/23/2015	6/23/2016	12/23/2016	none
D2MC-76083-LR	12/23/2015	6/23/2016	12/23/2016	none
EL4584CSZ-EVAL	12/23/2015	6/23/2016	12/23/2016	none
HA0-5127B5454-6	12/23/2015	6/23/2016	12/23/2016	none
ICM7244AIM44ZR5336	12/23/2015	6/23/2016	12/23/2016	ICM7244AIM44Z
ICM7244AIM44ZR5592	12/23/2015	6/23/2016	12/23/2016	none
ICM7244AIM44ZTR5336	12/23/2015	6/23/2016	12/23/2016	ICM7244AIM44ZT
ICM7244AIM44ZTR5592	12/23/2015	6/23/2016	12/23/2016	none
ISL1536IRZ-T13R5518	12/23/2015	6/23/2016	12/23/2016	none
ISL28208FBZ-T7S2752	12/23/2015	6/23/2016	12/23/2016	none
ISL28408FBZ-T7S2752	12/23/2015	6/23/2016	12/23/2016	none
ISL59442IBZ-EVAL	12/23/2015	6/23/2016	12/23/2016	none
ISL59530IKZ-EVAL	12/23/2015	6/23/2016	12/23/2016	none
ISL78022ANZ	12/23/2015	6/23/2016	12/23/2016	none
ISL78022ANZ-T	12/23/2015	6/23/2016	12/23/2016	none
ISL78022ANZ-TR5492	12/23/2015	6/23/2016	12/23/2016	none
ISL95810WIRT8ZR5481	12/23/2015	6/23/2016	12/23/2016	ISL95810WIRT8Z
ISL95810WIRT8ZTR5481	12/23/2015	6/23/2016	12/23/2016	ISL95810WIRT8Z-T
ISLEM-BDGSTKEV1Z	12/23/2015	6/23/2016	12/23/2016	none
ISLEM-TCSTKEV1Z	12/23/2015	6/23/2016	12/23/2016	none
ISLRE-BDGSTKEV1Z	12/23/2015	6/23/2016	12/23/2016	none
ISLRE-BDGSTKEV2Z	12/23/2015	6/23/2016	12/23/2016	none
ISLRE-BDGSTK-OPTEV2Z	12/23/2015	6/23/2016	12/23/2016	none
ISLRE-TCSTKEV1Z	12/23/2015	6/23/2016	12/23/2016	none
ISL THERMO-STKEV2Z	12/23/2015	6/23/2016	12/23/2016	none
TW2834-PA3-GES	12/23/2015	6/23/2016	12/23/2016	TW2834-PA3-GE
TW2974-LA1-CR	12/23/2015	6/23/2016	12/23/2016	none
TW3801-TC1-CRR5551	12/23/2015	6/23/2016	12/23/2016	TW3801-TC1-CR
TW3801-TC1-CRTR5551	12/23/2015	6/23/2016	12/23/2016	TW3801-TC1-CRT
TW3811-TC1-CRR5551	12/23/2015	6/23/2016	12/23/2016	TW3811-TC1-CR
TW3811-TC1-CRTR5551	12/23/2015	6/23/2016	12/23/2016	TW3811-TC1-CRT

Exact Intersil Part # No other variation is being impacted.	Notice PLC15066 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9429WS16IZ	12/23/2015	6/23/2016	12/23/2016	none
X9429WS16IZT1	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14IZ	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14IZ-2.7	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14IZ-2.7T1	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14IZT1	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14Z	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14Z-2.7	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14Z-2.7T1	12/23/2015	6/23/2016	12/23/2016	none
X9429WV14ZT1	12/23/2015	6/23/2016	12/23/2016	none
X9C103SIZT2	12/23/2015	6/23/2016	12/23/2016	X9C103SIZT1