

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)							
PCN #: A17 0	01-01	DATE 9-Feb-20	MEANS (OF DIST	INGUISHING (CHANGED I	DEVICES:
Product Affected	d: 4DB0226KA3AV0 (built in FCCSP-53		☐ Product ☐ Back II ☐ Date CI ☐ Other	Mark	Lot # will hav "B" prefix for		ι
Date Effective:	9-May-2017						
Contact:	IDT PCN DESK		Attachme	nt:	Yes		No
E-mail:	pcndesk@idt.com		Samples:	Please consample r	ontact your loca equest.	ıl sales repres	sentative for
DESCRIPTION	AND PURPOSE OF O	CHANGE:					
 □ Die Technology □ Wafer Fabrication Process □ Assembly Process □ Equipment □ Material □ Testing ■ Manufacturing Site □ Data Sheet □ Other 		This notification is to advise our customers that IDT is adding STATS ChipPAC Korea (SCK) as an alternate assembly facility for parts that are currently assembled at ASEK, Taiwan and ASECL, Taiwan. There is no change to the moisture performance. Attachment I details the qualification results.					
	QUALIFICATION SU ation data shown in Atta						
IDT records ind to grant approva it will be assume IDT reserves the	CKNOWLEDGMENT icate that you require wrall or request additional in the ed that this change is accertified to ship either version has been depleted.	ritten notification of thin formation. If IDT does eptable. sion manufactured after	s not receive ac	knowledg	gement within 30	0 days of this	notice
Customer:			☐ Appr	oval for	shipments p	rior to effe	ective date.
Name/Date:			E-Mail Addr	ess:			_
Title:			Phone# /Fax	#:			
CUSTOMER C	OMMENTS:						
IDT ACKNOW	LEDGMENT OF REC	CEIPT:					
RECD. BY:			DATE:				

Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA - 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A1701-01

PCN Type: Manufacturing Site - Alternate Assembly Location

Data Sheet Change: None

No change in moisture sensitivity level (MSL)

Detail Of Change:

This notification is to advise our customers that IDT is adding STATS ChipPAC Korea (SCK) as an alternate assembly facility for parts that are currently assembled at ASEK, Taiwan and ASECL, Taiwan.

The material set details of the current and alternate assembly location is as shown in Table 1.

There is no change to the moisture performance.

Table 1: Assembly Material Sets for The Existing and Alternate Assembly Location

	Existing Assembly (ASECL, Taiwan)	Existing Assembly (ASEK, Taiwan)	Alternate Assembly (SCK, Korea)
Die Bump	Sn1.8Ag	Sn1.8Ag	Sn1.8Ag
Mold Compound	KE-G1250FC-20B	KE-G1250FC-20B	KEG-1250FC-K
Substrate	ABF-GX13/E700GR core	ABF-GX13/E700GR core	ABF-GX13/E700GR core
Solder Balls	Sn/Ag1.2/Cu0.50/Ni0.05	Sn/Ag1.2/Cu0.50/Ni0.05	Sn/Ag1.2/Cu0.50/Ni0.05

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT I - PCN # : A1701-01

Qualification Information and Qualification Data:

Affected Packages: FCCSP-53

Assembly Material: Shown on page 2 of this attachment.

Qual Plan & Results: Tests are in accordance with JEDEC47 recommended tests.

Qualification Vehicle: FCCSP-53

Tost Description	Test Method	Test Results (Rej / SS)			
Test Description	Test Method	Lot 1	Lot 2	Lot 3	
* Temperature Cycling (-55°C to 125°C, 700 cycles)	JESD22-A104	0/25	0/25	0/25	
* HAST - biased (130 °C/85% RH, 96 Hrs)	JESD22-A110	0/25	0/25	0/25	
High Temperature Storage Bake (150°C, 1000 Hrs)	JESD22-A103	0/25	0/25	0/25	
Solder Ball Shear Test	JESD22-B117	0/5	0/5	0/5	
Moisture Sensitivity Level, MSL	J-STD-20 / MSL 3, 260 °C	0/25	0/25	-	

^{*} Tests were subjected to Preconditioning per JESD22-A113 prior to stress test