

## PRODUCT ADVISORY

## Data Sheet Specification Change for Intersil Product ISL6296A\*

Refer to: PA10039

**Date: April 15, 2010** 



April 15, 2010

To: Our Valued Intersil Customers

## Subject: Data Sheet Specification Change for Intersil Product ISL6296A\*

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL6296A\* products. The changes add guidelines for the selection of a series resistor to enhance ESD performance of the XSD and VDD pins. Modifications to the data sheet specification incorporating the changes are complete. The updated data sheet, FN6567 dated April 15, 2010, is included as a separate attachment with the changes shaded in yellow.

Products affected: ISL6296ADHZ-T ISL6296ADRTZ-T ISL6296ADRTZ-TR5302

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for screening of material supplied today.

If you have concerns with this change notice, Intersil must hear from you immediately. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Jon Brewster
Jon Brewster

Intersil Corporation PA10039

CC: J. Touvell T. Wolter L. Bradley