

Product Advisory (PA)

Subject: DA14585 Vbat Datasheet change

Publication Date: 5/10/2022

Effective Date: 4/13/2021

Revision Description:

N/A

Description of Change:

DA14585 datasheet rev3.4: Increase VBAT(VBAT3V) recommended operating condition max from 3.3V to 3.5V in section 3.2 table 3

Affected Product List:

DA14585-00000AT2			
DA14585-00000VV2			

Reason for Change:

Need to cover use cases that require additional operational headroom in nominal 3.3V powered applications.

Impact on Fit, Form, Function, Quality & Reliability:

The form, fit and function of the device will not be impacted by the change.

Product Identification: N/A

Qualification Status: Done

One lot HTOL (77 pcs) at 3.5V VBAT3V → All PASS

One lot LU (1.5 * Vmax) at +25°C and +85°C (6 pcs per temp.) → All PASS

Sample Availability Date: N/A

Device Material Declaration: N/A

For additional information regarding this notice, please contact your Renesas sales representative.