

Firmware Programming Y-COMMON-MB-T1-V1

If the mainboard “Y-COMMON-MB-T1-V1” does not have a firmware that complies with the tool “MB-Configurator” the firmware “Y-COMMON-MB-T1-V1_fw_V21.srec” must be programmed to the RL78 controller of the mainboard. Please follow the instructions:

- 1) Download the latest *Renesas Flash Programmer* from Renesas webpage:
www.renesas.com/rfp
- 2) Install *Renesas Flash Programmer*.
- 3) Connect any Renesas OCD emulator (E1, E2 or E2 lite) to your PC and start the *Renesas Flash Programmer*
- 4) Setup a new project for RL78 and program the above-mentioned firmware.