[Notification] End of Life (EOL): Renesas Starter Kits with E1 Emulator

R20TS0769EJ0100 Rev.1.00 Nov. 16, 2021

Outline

The production of the Renesas Starter Kits that include the EOL^{*} E1 emulator (E1 hereafter) is going to be discontinued (*end of life, i.e., end of production).

Please order the Renesas Starter Kits without E1 from now on.

1. Discontinued Products

1.1 Renesas Starter Kits for RX Family

Production discontinued		Replacement	
Name	Number	Name	Number
Renesas Starter Kit for RX111	R0K505111S000BE	Renesas Starter Kit for RX111 without E1	R0K505111S900BE
Renesas Starter Kit for RX113	R0K505113S000BE	Renesas Starter Kit for RX113 without E1	R0K505113S900BE
Renesas Starter Kit for RX210 (B Mask)	R0K505210S003BE	Renesas Starter Kit for RX210 (B Mask) without E1	R0K505210S903BE
Renesas Starter Kit for RX220	R0K505220S000BE	Renesas Starter Kit for RX220 without E1	R0K505220S900BE
Renesas Starter Kit for RX231	R0K505231S000BE	Renesas Starter Kit for RX231 without E1	R0K505231S900BE
Renesas Starter Kit for RX231 (B Mask)	R0K505231S020BE	Renesas Starter Kit for RX231 (B Mask) without E1	R0K505231S920BE*Note
Renesas Starter Kit for RX23T	RTK500523TS00000BE	Renesas Starter Kit for RX23T without E1	RTK500523TS90000BE
Renesas Starter Kit for RX24T	RTK500524TS00000BE	Renesas Starter Kit for RX24T without E1	RTK500524TS90000BE
Renesas Starter Kit for RX62T	R0K5562T0S000BE	Renesas Starter Kit for RX62T without E1	R0K5562T0S900BE
Renesas Starter Kit for RX630	R0K505630S000BE	Renesas Starter Kit for RX630 without E1	R0K505630S900BE*Note
Renesas Starter Kit for RX63T (64-pin)	R0K50563TS000BE	Renesas Starter Kit for RX63T (64-pin) without E1	R0K50563TS900BE
Renesas Starter Kit for RX63T (144-pin)	R0K5563THS000BE	Renesas Starter Kit for RX63T (144-pin) without E1	R0K5563THS900BE

*Note We will accept orders from January 2022.

1.2 Renesas Starter Kits for RL78 Family

Production discontinued		Replacement	
Name	Number	Name	Number
Renesas Starter Kit for RL78/G13	R0K50100LS000BE	Renesas Starter Kit for RL78/G13 without E1	R0K50100LS900BE
Renesas Starter Kit for RL78/G14	R0K50104PS000BE	Renesas Starter Kit for RL78/G14 without E1	R0K50104PS900BE
Renesas Starter Kit for RL78/G1C	R0K5010JGS000BE	Renesas Starter Kit for RL78/G1C without E1	R0K5010JGS900BE
Renesas Starter Kit for RL78/G1G	R0K5011EFS000BE	Renesas Starter Kit for RL78/G1G without E1	R0K5011EFS900BE
Renesas Starter Kit for RL78/L13	R0K5010WMS000BE	Renesas Starter Kit for RL78/L13 without E1	R0K5010WMS900BE
Renesas Starter Kit for RL78/L1C	R0K50110PS000BE	Renesas Starter Kit for RL78/L1C without E1	R0K50110PS900BE

2. Availability

The products are available as long as stocks last.



Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Nov.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/

> © 2021 Renesas Electronics Corporation. All rights reserved. TS Colophon 4.2

